

Validation of Unit 1 of the Fukushima Daiichi Nuclear Power Plant During its Accident

Shigenao Maruyama

Received: 5 June 2021 Accepted: 1 July 2021 Published: 15 July 2021

Abstract

Ten years have passed since the Great East Japan Earthquake and the subsequent accident at the Fukushima Daiichi nuclear power plant (NPP) that occurred on March 11, 2011. The earthquake and tsunami caused significant loss of lives and widespread disaster in Japan. Several reports have been published on the nuclear accident; however, the original data released at the beginning of the accident were written in Japanese, and some of these documents are no longer accessible. Some of the scenarios pertaining to the accident have become standardized theories, and these scenarios may be passed down to future generations with different descriptions, which may not fully describe the actual occurrences. To prevent future nuclear accidents, the accident at Fukushima Daiichi must be properly understood and analyzed.

Index terms— nuclear power plant, accident, isolation condenser, thermodynamic model, fukushima daiichi, great east japan earthquake.

Validation of Unit 1 of the Fukushima Daiichi Nuclear Power Plant During its Accident Shigenao Maruyama
Abstract—Ten years have passed since the Great East Japan Earthquake and the subsequent accident at the Fukushima Daiichi nuclear power plant (NPP) that occurred on March 11, 2011. The earthquake and tsunami caused significant loss of lives and widespread disaster in Japan.

Several reports have been published on the nuclear accident; however, the original data released at the beginning of the accident were written in Japanese, and some of these documents are no longer accessible. Some of the scenarios pertaining to the accident have become standardized theories, and these scenarios may be passed down to future generations with different descriptions, which may not fully describe the actual occurrences. To prevent future nuclear accidents, the accident at Fukushima Daiichi must be properly understood and analyzed.

Our research group had been analyzing the accident since immediately after its occurrence [2]. To investigate the process of the NPP accidents, Unit 1 of the Fukushima Daiichi NPP was analyzed using data available to the public. A phase equilibrium thermodynamic model was used in the analysis. We proposed an accident scenario in which the isolation condenser (IC) of Unit 1 may have been working to a certain extent. Moreover, the behavior of the reactor water level meter at the time of the accident was analyzed, and we attempted to reproduce the measurement data of the reactor water level meter and the pressure data measured during the accident. Furthermore, based on the temperature data of various measuring points and the estimated accident scenario of Unit 1, we also presented a bold estimation of the locations and times of damages in the reactor pressure vessel (RPV) and primary containment vessel (PCV).

In the present study, the original data reported in the first stage of the accident are examined to clarify the behavior of the ICs, which are generally believed to have been nonfunctional after the tsunami and station blackout. The original data and observation reports verified that the so called "fail-safe" system to close the valves in the ICs did not work properly owing to the shutdown of AC power.

This report assumes that the leakage of the RPV occurred at 20:26 on March 11, 2011 owing to overheat of the nuclear fuel clusters. It is estimated that the leakage of the PCV occurred at 03:30 on March 12. A large break in the RPV occurred at 06:20 and again at 16:00. It is estimated that a large portion of the fuel still remains in the RPV; however, the Tokyo Electric Power Company (TEPCO) estimated that most of the fuel had

46 melted out through the RPV. The present analysis model and accident scenario explain the data measured at
47 the accident and several evidences and witness reports that were collected at the early stage of the accident.

48 Author: President, National Institute of Technology, Hachinohe College, Hachinohe, Aomori, 039-1192 Japan.
49 e-mail: shigenao.maruyama@gmail.com Introduction en years have passed since the Great East Japan Earthquake
50 and the subsequent accident at the Fukushima Daiichi nuclear power plant (NPP).

51 Approximately one hour before the occurrence of the earthquake at 14:46 on March 11, 2011, the author had
52 landed at Sendai Airport, Japan, on his way back home from a business trip in the People's Republic of China.
53 Three hours after his arrival, the airport was seriously damaged by the tsunami. Hereinafter, the time described
54 is based on the Japan Standard Time. When the author returned to his home in Sendai city, he encountered the
55 earthquake. His home was damaged by the earthquake.

56 The earthquake and tsunami caused significant loss of lives and widespread disaster in Japan. More than
57 15,000 people were killed, and approximately 2,500 people are still reported to be missing [??1].

58 At the Fukushima Daiichi NPP, the earthquake caused damages to the external electric supply required to
59 operate the plant. The subsequent tsunami attacked the NPP, resulting in the loss of the cooling function at
60 the three operating reactor units. Then, accumulation of hydrogen gas occurred in the reactor buildings (R/Bs),
61 resulting in explosions at Units 1 and 3. After the reactor cores of Units 1-3 were damaged, a large amount
62 of radioactive materials were released into the atmospheric environment. The water used for the cooling of the
63 damaged reactor cores was contaminated by radioactive substances, which was then spilled and released into the
64 sea.

65 1 T

66 The author started exchanging information regarding the NPP on March 15. At that time, the possibility of
67 nuclear fuel core blockage due to seawater injection was being discussed with his acquaintances who were nuclear
68 power professionals. The author estimated the current state of the NPP with the help and guidance of nuclear
69 engineering experts and colleagues in academic communities, and disseminated information for early convergence
70 of the accident.

71 Sendai, where we lived, is located 95 km north of the Fukushima Daiichi NPP. The thermo-fluid analysis of the
72 NPP was conducted using the electric power and the internet restored relatively quickly after the earthquake. We
73 left half of the gasoline in the tanks of our automobiles for the preparations to evacuate from Sendai if something
74 happened to the NPP.

75 At the first stage, information was distributed to experts in the field of thermal engineering and to the personnel
76 of the Tokyo Electric Power Company (TEPCO), who were introduced by our colleagues. To disseminate
77 information to the public as soon as possible, the Heat Transfer Control Laboratory of the Institute of Fluid
78 Science, Tohoku University, began distributing heat-and-flow-analysis reports on its website from March 28 [2].
79 Our laboratory posted 26 reports in the two months from March 28 to ??ay 30, 2011. The total number of
80 reports increased to 48 by ??arch 3, 2015. We started to estimate the decay heat of each unit from open data
81 source, and the data were published on the website [HTC Rep. 1.1, 2011/3/28]. Hereinafter, this report [2] is
82 described as [HTC Rep.#, issued date]. This estimation was corrected, including the operating history of nuclear
83 fuel units [HTC Rep. 1.4, 2011/4/13]. At the time of release of the report, our estimation of the decay heat was
84 different from that provided by TEPCO; however, the estimation presented by TEPCO at the later date became
85 almost identical to our data.

86 We estimated the steam generation rate of each unit and calculated the ruptured area of the primary
87 containment vessels (PCVs) using the plant parameters such as pressure and temperature. The flow rate
88 calculation method utilizing an orifice was applied to the analysis. We reported that the estimated ruptured
89 area on the PCV of Unit 1 was equivalent to a diameter of 9 cm and that on the suppression chamber (S/C) of
90 Unit 2 was 20 cm, based on the plant parameters obtained on March 26, 2011 [HTC Rep. 14.2, 2011/5 ??11]. The
91 ruptured area on the PCV of Unit 3 was estimated to be equivalent to a diameter of 23 cm based on the plant
92 parameters obtained on May 3. The Japanese government and TEPCO had not announced that the PCVs of
93 Units 1-3 were ruptured when we released the report on May 11. Then TEPCO announced on May 25 that the
94 PCVs of Units 1 and 2 may have ruptured, and the equivalent diameters of the ruptures on Units 1 and 2 were
95 7 and 10 cm, respectively.

96 TEPCO published an estimation of fuel core conditions of Units 1-3 on May 16, 2011 [3], using a large computer
97 simulation code "Modular Accident Analysis Program (MAAP)." It was reported that the operator restarted the
98 isolation condenser (IC) system A (IC-A) of Unit 1 at 18:18, on March 11, and the ejection of steam from the
99 R/B was confirmed. It was stopped at 18:25, and restarted again at 21:30.

100 However, TEPCO assumed that the IC of Unit 1 did not work after the station blackout. According to the
101 analysis based on MAAP, the fuel core was damaged 15 h after the tsunami attack, and all the fuel melted out
102 from the reactor pressure vessel (RPV). TEPCO mentioned that "From the analysis results, fuel core damage
103 started relatively early after the arrival of the tsunami, resulting in damage to the RPV. However, considering the
104 state of the plant estimated from the temperature shown below, the analysis seems to be a severe consequence"
105 [3]. However, TEPCO maintained the assumption that the IC did not work in their subsequent reports [6], [12].

106 After this announcement [3], all mass media reported sensationally that the Fukushima Daiichi NPP had
107 melted down. TEPCO also assumed that the IC of Unit 1 was not functional after the station blackout caused

108 by the tsunami. This assumption was followed by a government report [4] stating that "Unit 1 lost its all
109 power supplies shortly after the arrival of the tsunami. The isolation condensers (IC) seemed to have lost its
110 functionality as its isolation valves were fully or almost fully closed by the fail-safe circuits." The International
111 Atomic Energy Agency (IAEA) followed this assumption [5].

112 However, some key evidences showed that the IC was working. For example, there are original records that
113 the operator restarted IC-A, and steam ejection was observed from the R/B. There are records that the water
114 was injected into the reservoir tank of the IC. As presented in Section 3, the reactor water level indicator shows
115 the correct value when the water level is above the top of active fuel (TAF). The records of the water level meter
116 show that the measured water levels were above the TAF at almost constant values from 21:30 on March 11 to
117 06:30 on March 12. TEPCO explained in the report on June 20, 2012, that "Therefore, water levels measured
118 after core damage are assumed to be unreliable, while water levels taken via analysis are assumed to be closer to
119 those in reality" [6].

120 We assumed that the IC was, to a certain extent, functional after the station blackout, and estimated that the
121 breakdown of the RPV occurred considerably later than the estimation presented by TEPCO [HTC Rep.17.2,
122 2011/5/30]. In the analysis, a simple energy balance [HTC Rep. 1.4, 2011/4/13] was considered. The details
123 are described in a published paper [7]. We constructed a more detailed thermodynamic model to describe the
124 equilibrium state of the RPV and PCV of each unit. We determined that the measured data and original record
125 were well described by the simulation using a thermodynamic model.

126 2 Volume Xx XI Issue I V ersion I

127 Global Journal of Researches in Engineering ()

128 3 F

129 The simulation program used by TEPCO, the MAAP, is a large system; moreover, it requires a relatively long
130 central processing unit (CPU) time to calculate one accident scenario. Conversely, our program is small and was
131 operated in Microsoft Excel. Our simulation can be used to calculate one set of the accident scenarios within a
132 few seconds, and related diagrams are illustrated promptly. This significantly short turnaround time helped us
133 to simulate large number of accident scenarios to fit the measured plant parameters at the time of the accident.
134 In the analysis of Unit 1, we estimated that the IC was functional until around 03:00 on March 12, 2011 [HTC
135 Rep.26.1 2013/02/10], [9].

136 The Atomic Energy Society of Japan estimated that the AC-driven valve of the IC was fully open when the
137 tsunami struck, and questioned the scenario in which the IC did not work at all after the arrival of the tsunami
138 [10]. The Nuclear Regulation Authority of Japan (NRA) examined the status of the IC valves at the time of the
139 tsunami attack, and reported that "However, the operating status (open/close) of isolation valves (1A and 4A)
140 of the IC (system "A") in the PCV is not clear. It is therefore necessary to continue analyses of this issue." [11].
141 TEPCO followed up the report [6] on unsolved issues in the accident progression and published additional reports
142 [12] - [16]. TEPCO carried out a simulation where the IC was working in the third progress report [14], which
143 was published on May 20, 2015. The report stated that "But in the overall progression of the accident it would
144 be quite likely the there is a minor difference from what actually occurred in Unit1." There was no explanation
145 in the report on why the measured water level showed constant values in the early stages of the accident.

146 Our accident scenario assumed that the IC was functional until approximately 03:00 on March 12, 2011 [HTC
147 Rep.26.1 2013/02/10], [9]. This scenario can explain the measurements of the reactor water level in the early
148 stages of the accident. The reactor water level meter shows different value from reality when the water level is
149 below the TAF. We could reproduce the measured water level data by considering the structure of the reactor
150 water level meter [HTC Rep.32.2, 2014/03/05]. We could also reproduce the data when the water level was lower
151 than the TAF. TEPCO attempted to reproduce the measured data of reactor water levels based on the scenario
152 proposed by TEPCO in the fourth progress report [15], which was presented on December 17, 2015, which is 1.5
153 years later than our report.

154 According to the above-mentioned analysis using the thermodynamic model and plant parameters on October
155 10, 2012, we estimated the location of rupture on the PCV [HTC Rep.25.1, 2012/12/26], [9], and we presumed
156 that the location of the rupture was at the bellows that connects the bottom of the dry well (D/W) and the S/C
157 of the PCV. TEPCO examined the interior of the R/B using a robot and determined on May 27, 2014 that water
158 was leaking from the cover of an expansion joint on a vacuum break line; moreover, they estimated that the
159 rupture occurred at the vacuum breaker tube bellows near the bottom of the D/W. This location is considerably
160 close to the location estimated by us on December 26, 2012, which was 1.5 years before the findings of TEPCO
161 [13].

162 In our analysis [HTC Rep.26.1 2013/02/10], [9], we assumed a very small leakage from a rupture equivalent to
163 a diameter of 0.86 cm on the RPV of Unit 1. The NRA examined the plant data immediately after the tsunami
164 attack, and reported that "The NRA could not find any plant data indicating the coolant leak from the reactor
165 pressure boundary between the earthquake occurrence and the tsunami arrival" [11].

166 Based on this finding, we proposed a new accident scenario in which a small leakage occurred at a safety valve
167 (SV) of the RPV at 20:26 on March 11, 2011, and a large leakage occurred at 06:20 on March 12 at another

168 SV [HTC Rep.35.1, 2015/03/03]. The rest of the second scenario was similar to the previous one [9]. We also
169 boldly anticipated the locations of the rupture on the RPV of Unit 1 according to the temperature data after
170 the accident [HTC Rep.32.2, 2014/03/05].

171 According to our accident scenario and the simulation of Unit 1 [HTC Rep.35.1, 2015/03/03], it was estimated
172 that fuel leakage occurred approximately at 16:00 on March 12, 2011, which was considerably later than the
173 estimation presented by TEPCO [16]. Moreover, we estimated that a significant portion of the fuel remains
174 in the RPV. This estimation was verified by the temperature data of the unit obtained after March 21 [HTC
175 Rep.32.2, 2014/03/05]. TEPCO estimated that all the fuel in the RPV had leaked out and mentioned that "most
176 of the molten fuel generated at the accident fell down to the lower plenum below the reactor pressure vessel" [16].

177 We performed a similar simulation of Unit 2 using a similar thermodynamic model, and these results are
178 published in [8]. Our accident scenario and simulation results pertaining to Unit 2 show results similar to those
179 of TEPCO [16], which were determined using the large simulation code MAAP. Our result pertaining to Unit 2
180 shows better agreement with the measured data at the accident than the analysis presented by TEPCO.

181 We conducted a simulation of Unit 3 using a similar thermodynamic model, and these results are published in
182 [17] and [18]. Our simulation results are different from those of TEPCO. We estimated that the PCV of Unit 3
183 ruptured at 09:05 on March 13, 2011. We estimated the ruptured area using the plant parameters and decay heat
184 at the accident and determined that the equivalent diameter of the ruptured area was 15 cm Volume Xx XI Issue
185 I V ersion I Global Journal of Researches in Engineering () F © 2021 Global Journals [17]. The temperature in
186 the PCV and RPV of Unit 3 is considered to have increased on March 22, because the water injection into the
187 reactor core became significantly small. We estimated that the ruptured area increased to approximately five
188 times larger size than the initial one. It is estimated that the seal on the upper flange of the PCV was damaged
189 on March 22 caused by the hightemperature condition at that time [17].

190 TEPCO estimated that the decrease in pressure in Unit 3 on the morning of March 13 was due to the fact
191 that the safety relief valve (SRV) was opened, and the vent was operated successfully [6]. On May 2014, water
192 leaks were identified around the expansion joint where the PCV penetrated the main steam pipe D [13]. This
193 indicates that leakage occurred at the bellows of the expansion joint. This finding supports our estimation at
194 that time pertaining to the rupture of the PCV [17]. The NRA confirmed that there was strong contamination
195 on the underside of the shield plug installed on top of the PCV of Unit 3 [19]. This may support the fact that
196 the seal on the upper flange of the PCV was damaged [17].

197 The author published a book describing the progress of the accident at the Fukushima Daiichi NPP [20].
198 The events pertaining to the Fukushima Daiichi NPP, Units 1-4, that are dealt with in this book are based on
199 the reports [2] published up to August 2012. The behaviors of the Japanese Prime Minister, Cabinet members,
200 TEPCO executives, and the Director of the Fukushima Daiichi NPP were described based on the facts reported in
201 mass media during and after the accident. Their behavior was described to synchronize with the accident scenarios
202 of Units 1-4 that were presented in our report [2]. Comparing the content of this book with the testimony of the
203 Director of the Government Accident Independent Investigation Commission [21] published after the publication
204 of the book [20], both reports agreed well [HTC Rep.33.1, 2014/6/22]. The words and actions of the members
205 of the office of the Prime Minister and those of the TEPCO executives also agreed well with the reports in this
206 book [20].

207 The book was written based on our accident scenario before August 2012. However, there are several
208 discrepancies in the analysis of the author [7]. For example, in the first scenario by [7], the author cannot
209 describe why the radiation dose in the R/B increased on March 11at 21:51, while the water level at that time
210 was above the TAF. The pressure in the RPV was high when water was injected at 06:20 on March 11 and water
211 could not be injected under the previous scenario.

212 TEPCO reported that the injected water may not have reached the RPV because the bypass line was
213 constructed in the reactor system. Consequently, based on the findings of the bypass line, the author constructed
214 a new scenario and analyzed the pressure and water level of Unit 1 [HTC Rep.26.2, 2013/03/03] using a
215 thermodynamic model to analyze the accident behavior of Unit 1. The previous accident scenario [9] assumed a
216 small leak in the RPV immediately after the earthquake. The PCV was estimated to rupture at 03:00 on March
217 12 and the RPV rupture occurred at approximately 06:20 and 16:00 on March 12. The IC was estimated to be
218 functional until approximately 03:00 on March 12. The pressure estimations of the PCV and RPV were in good
219 agreement with the measured data [HTC Rep.26.2, 2013/03/03].

220 The Atomic Energy Society of Japan reported that the initial leak of the RPV may not have occurred, according
221 to the measured data of the PCV obtained before the arrival of the tsunami [10]. This fact indicates that the
222 scenario [9] that assumes the initial leak of the RPV may not be suitable.

223 Ten years have passed since the accident at the Fukushima Daiichi NPP. According to TEPCO, the
224 decommissioning process is expected to be completed in another 20-30 years. Several reports have been published
225 on the nuclear accidents, such as [4], [5], [10], [??23]. However, the original accident data and records are gradually
226 becoming lost. Some of the original data released at the beginning of the accident are no longer accessible. Certain
227 scenarios of the accident, which is different from what actually happened, have become standardized theories
228 and may be passed down to future generations. To prevent future nuclear accidents, the accident at Fukushima
229 Daiichi must be properly understood and analyzed. Our analysis of the accident [2] may not always be accurate.

230 Even our latest accident analysis may not agree with the actual measured data, or with our own records at the
231 time.

232 In this study, we verified that if the IC of Unit 1 of the Fukushima Daiichi NPP may have been working normally
233 to a certain extent, and performed an analysis based on that accident scenario. Moreover, the behavior of the
234 reactor water level meter at the time of the accident was analyzed, and an attempt was made to reproduce the
235 measurement data of the reactor water level meter during the accident. Furthermore, based on the temperature
236 data of various measuring points and the estimated accident scenario of Unit 1, we also make a bold estimation
237 of the damaged positions of the RPV and PCV of Unit 1 as well as the times of the damage.

238 4 II.

239 Outline of the Accident at The Fukushima Daiichi Nuclear Power Plant

240 The Great East Japan Earthquake occurred on March 11, 2011 at 14:46. The epicenter was 130 km east-
241 southeast of the Oga Peninsula in the Pacific Ocean. This earthquake was caused by an energy release at the
242 border of the Pacific tectonic plate and the North American tectonic plate. The earthquake had a Volume Xx
243 XI Issue I V ersion I Global Journal of Researches in Engineering () F magnitude of 9.0, and the tremors lasted
244 for more than two minutes.

245 Tsunamis following the earthquake struck a wide area of the northeastern coast of Japan. Several waves
246 reached heights of more than 10m, the largest since the Jogan Earthquake, which occurred in the year of 869,
247 approximately 1150 years ago. The earthquake and tsunami caused significant loss of lives and widespread
248 disaster in Japan. More than 15,000 people were killed, and approximately 2,500 are still reported to be missing
249 [1].

250 At the Fukushima Daiichi NPP, operated by TEPCO, the earthquake caused damage to all external electric
251 supplies required to operate the plant. The subsequent arrival of the tsunami at the NPP destroyed the emergency
252 power supplies and the operational safety infrastructure on the site. This resulted in the loss of the cooling
253 function at the three operating reactor units.

254 Consequently, the reactor cores in Units 1, 2, and 3 were overheated owing to the decay heat of the nuclear
255 fuel, and the three PCVs ruptured. Hydrogen gas was released from the RPVs and leaked through the PCVs.
256 The hydrogen gas accumulated in the R/Bs, which resulted in explosions in Units 1 and 3.

257 Radio nuclides were released from the NPP to the atmosphere and were deposited on land. The radioactive
258 water that is used to cool the plant was released directly into the sea. People within a radius of 20 km from
259 the NPP site and in other designated areas were evacuated. Those within a radius of 20-30 km were advised to
260 voluntarily evacuate. Ten years after the accident, many people still live outside the evacuated areas.

261 Details of the accident before 2015 have been presented in many reports, such as [4], [5], [10], [23]. The interior
262 of the reactors has not yet been revealed. The amount of cooling water that is contaminated by tritium is still
263 increasing, and the storage tanks will be full at the NPP site. The Japanese government is planning to release
264 the contaminated water into the ocean by diluting it with seawater.

265 An outline of the accidents occurred in Units 1-6 is subsequently presented.

266 5 a) Before the Tsunami Attack

267 The Fukushima Daiichi NPP in Fukushima prefecture consisted of six units of boiling water reactors (BWRs),
268 as listed in Table 1. The BWR units were constructed between 1971 and 1979, and the oldest unit had been in
269 operation for 40 years at the time of the accident. During the operation, several facilities have been replaced,
270 except for the primary structures such as the RPVs, PCVs, and buildings.

271 When the earthquake occurred, Units 1, 2, and 3 were operating at full power, and Units 4, 5, and 6 were
272 shut down for periodic inspection and maintenance. Unit 4 was stopped for repairing the shroud in the PRV.
273 The spent fuel pool of Unit 4 contained more than 1,300 spent fuel and active fuel assemblies from the reactor.
274 Units 5 and 6 were shut down for periodic inspection, and the fuel assemblies were in the PRVs.

275 6 Volume

276 7 Periodic inspection

277 Fig. ???: Overview of the boiling water reactor plant before the tsunami attack [20] BWRs use a steam cycle loop,
278 as shown schematically in Fig. ?. Coolant water boils in the reactor core at a pressure of approximately 7 MPa,
279 and the generated steam is used to drive turbines to generate electricity. After passing through the turbines, the
280 steam is condensed back to water in condenser tubes that are circulated with cold sea water. The water resulting
281 from condensation is pumped back to the reactor as feed water.

282 In the case of the Fukushima Daiichi NPP, the produced electricity was delivered to the Tokyo area. NPPs
283 require an external power supply to operate the plants. This electric power was supplied by the Tohoku Electric
284 Power Company because the location of the Fukushima Daiichi NPP is within the jurisdiction of this company,
285 which is different from the Tokyo Units 1-4 were built 10 m above sea level, and Units 5 and 6 were on the
286 ground level, 13 m above sea level. Units 1 and 2 were controlled by a main control room, and Units 3 and 4
287 were controlled by another main control room. A seismically isolated building was constructed for an emergency

288 accident of the NPP one year before the accident. This building had emergency Electric Power Company
289 (TEPCO). This external electric power is used to cool down the fuel core after the NPP is shutdown.

290 Volume Xx XI Issue I V ersion I Global Journal of Researches in Engineering () F electric generators and air
291 cleaners to prevent the entry of radio active materials into the building. A local emergency headquarter was set
292 up in the building in the occurrence of an accident.

293 When the Great East Japan Earthquake of magnitude 9 occurred, the recorded maximum acceleration at the
294 Fukushima Daiichi NPP was 550 gal. The operating reactors of Units 1, 2, and 3 were shut down automatically
295 and the fission reaction in the reactor cores was stopped. However, these reactors had to be cooled because decay
296 heat was generated inside the reactor cores. The earthquake caused damage to the switchboard equipment, and
297 the external AC power supply from Tohoku Electric Company to the plant was shut down. The emergency diesel
298 generators automatically started to restore the AC power in all six units. The ICs in Unit 1 started automatically
299 to cool the reactor. The operators manually activated the reactor core isolation cooling systems (RCICs) in Units
300 2 and 3.

301 8 b) After the Tsunami Attack

302 The initial tsunami waves arrived at the NPP approximately 40 min after the earthquake. The site was protected
303 from the first wave by a barrier seawall, which was designed to protect the land against a tsunami of 5.5 m height.
304 The second tsunami wave arrived at 15:36. It was estimated to be more than 14.5 m high. This tsunami attacked
305 the NPP and destroyed the emergency diesel generators and DC batteries. A station blackout was declared for
306 Units 1-5 at 15:42. The residual heat removal system (RHR) did not function because of the station blackout.

307 At the time of the tsunami attack, the situation at each unit was as described subsequently.

308 Unit 1: The emergency diesel generators were damaged, and the AC power was lost. The DC batteries became
309 nonfunctional owing to the invasion of seawater. IC system B (IC-B) was manually stopped before the tsunami
310 attack, and IC-A was manually operated before the arrival of the tsunami. When the tsunami hit the NPP, the
311 valve of IC-A was closed, and the IC was not activated.

312 Unit 2: The emergency diesel generators were damaged, and the AC power was lost. The DC batteries became
313 nonfunctional owing to the invasion of seawater. The RCIC was started just after the arrival of the tsunami.
314 Fortunately, the RCIC worked until 13:00 on March 14, without the DC power.

315 Unit 3: The emergency diesel generators were damaged, and the AC power was lost. The DC batteries survived
316 against the tsunami attack. Using the DC power, the emergency core cooling systems were operated until 02:42
317 on March 12.

318 Unit 4: The fuel assemblies from the reactor fuel were stored in the spent fuel pool, and the fuel was generating
319 decay heat. The cooling function of the spent fuel pool was lost owing to the loss of the external power supply
320 and emergency generators. Units 5 and 6: The batteries were not damaged, and DC power was available. An
321 air-cooled emergency diesel generator in Unit 6 survived the tsunami attack. Using the AC power from this
322 operational generator, the operators managed to cool the decay heat in the reactor cores. Finally, the reactors
323 stabilized. The radiation level at the main gate of the NPP increased at 04:00 on March 12, and TEPCO
324 attempted to inject water into Unit 1. An explosion occurred in the R/B of Unit 1 at 15:36. The explosion
325 damaged the R/B; however, the PCV was not damaged. This explosion was caused by the accumulation of
326 hydrogen gas that was generated by the chemical reaction between the high-temperature zirconium and water
327 vapor in the fuel core.

328 Unit 3: Immediately after the tsunami attack, the DC batteries of Unit 3 were functional, even though the
329 emergency AC generators were nonfunctional. Hence, the RCIC of Unit 3 was working at that time. The RCIC
330 became in operative at 11:36 on March 12; then, the high-pressure coolant injection system (HPCI) started
331 automatically owing to the low water level in the RPV. The HPCI was stopped at 02:42 on March 13. Fresh
332 water was injected into the RPV at 09:25, and the seawater was injected at 13:25 by venting the internal gas
333 into the environment. An explosion occurred at 11:01 on March 14 in the R/B. This explosion was caused by the
334 accumulated hydrogen gas that was generated by a chemical reaction between the hightemperature zirconium
335 and water vapor in the fuel core of Unit 3.

336 9 d) Rupture of the PCV of Unit 2 and the Explosion of the

337 Reactor Building of Unit 4 Unit 2: According to the report of TEPCO [6], the RCIC repeated an automatic stop
338 function owing to water level in the RPV and manual restarting was performed before the tsunami attack. The
339 RCIC was stopped automatically at 15:28, and the tsunami attacked Unit 2 at approximately 15:35. The operator
340 restarted the RCIC manually at 15:39. Owing to the tsunami attack, the emergency diesel AC generators and DC
341 batteries in Unit 2 became nonfunctional at approximately 15:41. The RCIC was working, and the appropriate
342 valves were open when the blackout occurred.

343 Fortunately, the RCIC of Unit 2 was working without electricity. It was presumed that the turbine and pump
344 powers were balanced and the RCIC continued working for almost 70 h without any control after the blackout.
345 Finally, the RCIC became nonfunctional at 10:30 on March 14.

346 The seawater injection into the RPV started at 19:54 on March 14, and the pressure in the RPV was reduced
347 by manually opening the SRV. Owing to the release of the internal gases of the RPV into the PCV, the pressure

348 in the PCV increased; however, the pressure in the PCV could not be reduced because the depressurization by
349 venting was unsuccessful.

350 Owing to the pressure increase in the PCV, the PCV ruptured at approximately 06:00-08:00 on March 15, and
351 a large amount of radioactive materials was released into the environment. White smoke or steam was observed
352 near the fifth floor in the R/B of Unit 2. The radiation dose measured at the main gate at approximately 09:00
353 was 12mSv/h, which was the highest since the beginning of the accident.

354 Unit 4: Vibrations due to the explosion were reported at 06:14 on March 15 by the operators in the main
355 control room of Units 1/2. These vibrations were caused by the explosion of the R/B of Unit 4 at 06:12 [6]. The
356 evacuating personnel reported that the upper part of the R/B blew out at approximately 06:00 on March 15.

357 It was presumed that this explosion was caused by the hydrogen gas released from Unit 3. The process of
358 venting the internal gases and steam was repeated in Unit 3 after its explosion at 11:01 on March 14. This venting
359 process was conducted using the standing gas treatment system (STGS) line and the exhaust stack. Units 3 and
360 4 used the same exhaust stack, and the STGS lines of Units 3 and 4 were connected. TEPCO estimated that
361 a part of the produced hydrogen gas in Unit 3 was accumulated in the R/B of Unit 4, and the hydrogen gas
362 exploded.

363 The spent fuel pool on the fifth floor of the R/B of Unit 4 contained more than 1,300 fuel assemblies, including
364 the active fuel assemblies from the reactor. These fuel assemblies from the reactor core produced a large amount
365 of decay heat. The cooling function of the spent fuel pool was lost owing to the blackout of Unit 4.

366 The US government was concerned with the blackout and explosion of Unit 4, and the damage to the
367 spent nuclear fuel pool, which could result in a large discharge of radioactive materials. Consequently, the US
368 government issued an evacuation advisory to Americans staying within a radius of 50 miles from the Fukushima
369 Daiichi NPP on March 16. However, it was confirmed that water existed in the pool; moreover, water was filled
370 stably into the pool using concrete pump vehicles from March 22.

371 10 e) Release of Radioactive Materials

372 After the reactor cores of Units 1-3 were damaged, water was injected into the RPVs. The evaporated steam and
373 radioactive materials were released into the atmospheric environment. Immediately after the explosions of the
374 R/Bs, seawater was injected, followed by the injection of fresh water from March 25. The spilled water that was
375 contaminated by the radioactive materials was released into the sea through the trench, which is an underground
376 tunnel for storing pipelines and cables.

377 The IAEA [5] reported that the released mean total activity of ^{131}I (half-life time is 8 days) was 100-400
378 PBq, and that of ^{137}Cs (half-life time is 30 years) was approximately 7-20 PBq. The unit, 1peta-bequerel,
379 equals 10^{15} Bq. The release of radioactive materials owing to the accident was estimated to be Volume Xx XI
380 Issue I V ersion I Global Journal of Researches in Engineering () F approximately one-tenth of the radioactive
381 materials released owing to the accident in 1986 at the Chernobyl NPP. The direct release of ^{131}I into the sea
382 was estimated to be 10-20 PBq, and that of ^{137}Cs was approximately 1-6 PBq.

383 TEPCO constructed a contaminated water cycle, as shown in Fig. 3. The spilled-out contaminated water
384 from the broken RPVs was pumped up and stored in a temporary storage tank. The oil was removed from
385 the contaminated water, and cesium was removed using a facility called Simplified Active Water Retrieve and
386 Recovery System; further, strontium and other radioactive materials were removed using an Advanced Liquid
387 Processing System. The decontamination equipment cannot remove tritium because hydrogen and tritium are
388 the same chemically and physically. The decontaminated water was desalted using a nano-pore film. Purified
389 clean water was injected into the highly contaminated RPVs to cool the decay heat.

390 This water cycle is basically maintained at present. Water in the outside soil flows into the basement of the
391 reactor and turbine buildings, and it is stored in the tanks constructed on the NPP site. The cooling water
392 contaminated with tritium is increasing, and storage tanks are full on the NPP site. The Japanese government
393 is planning to release the contaminated water into the ocean by diluting it with seawater.

394 Fig. 3: Status of the contaminated water cycle, as of August 2011 [24] During the Fukushima Daiichi NPP
395 accident, no one was killed by acute radiation syndrome, which is caused by direct irradiation from the radioactive
396 materials released owing the accident. It was reported that 28 emergency workers were killed because of the acute
397 radiation syndrome within four months of the Chernobyl accident in 1986.

398 Many people were killed during the evacuation process. For example, 388 elderly patients in a hospital within
399 a 20 km radius were evacuated in normal buses after the explosion of Unit 3. They are transported without
400 proper care, and 21 died during and after the evacuation process. Many other people died after the evacuation
401 owing to mental and physical diseases caused by the evacuation. Unit 1 of the Fukushima Daiichi NPP was the
402 oldest unit in the NPP and was equipped with ICs for emergency cooling. When a reactor scrams, and the fission
403 reaction stops, the IC cools the decay heat of the fuel cores. The steam released by the decay heat enters the
404 heat transfer tube installed in the IC, and it is condensed by the water in the IC reservoir tank. The condensed
405 water returns to the reactor. The water in the IC reservoir tank evaporates, and steam is released from the R/B.
406 The cooling process by the IC can function without external electric power.

407 Figure ?? shows the emergency cooling system using the ICs and their valve positions. Four valves connecting
408 each IC and the RPV are attached to IC-A and IC-B. These valves are motor-operated valves (MOVs), which
409 hold their position "as it is" when the electric power supply stops. MOV-1 and MOV-4 are AC motor-driven

410 valves, and MOV-2 and MOV-3 are DC motor-driven valves. The positions of the valves are shown in Fig. ??.
 411 MOV-3A and MOV-3B, of systems A and B, respectively, are closed and the other valves are open when the
 412 reactor is in operation. The reservoir tank of the IC is connected to a filtered water tank. The water is supplied
 413 by a diesel-driven fire pump (D/D FP) when the IC is operated for a long time.

414 When the reactor was stopped by a scram due to the earthquake, the ICs started automatically. The operator
 415 stopped system B, i.e., the operator closed MOV-3B. Moreover, system A was intermittently operated to maintain
 416 the temperature decrease of the reactor within 55 °C/h (100 °F/h). Just before the tsunami attack at 15:36,
 417 MOV-3A was closed at 15:34 by the operator. As discussed in Section 3.3, the reactor water level meters showed
 418 constant values in the early stages of the accident. This measurement data is important for verifying the behavior
 419 of the IC. Figure 5 shows a schematic of the reactor water level meter. The water level of a BWR is measured by
 420 the water head difference between the water level of the reactor fuel region Z F and the water level Z Ref of the
 421 reference condensing water chamber, which is placed outside the RPV. The water level of the reactor fuel region
 422 Z F is expressed as $Z F = H F - L F$ in Fig. 5, when Z F is lower than the TAF. The reference condensing water
 423 chamber is connected to the PRV by a tube. The difference in water heads between Z F and Z Ref is measured
 424 by a pressure gauge placed outside the PCV.

425 11 Volume

426 The temperature of the reference condensing water chamber is marginally lower than that of the RPV. Hence, the
 427 saturated water vapor in the RPV flows in the chamber and condenses to water in the chamber. The condensed
 428 water in the chamber flows back to the RPV. Hence, the water level of the reference Z Ref is equal to L 1 .
 429 Accordingly, the water level meter shows a constant water head when the water level of the RPV is higher than
 430 the TAF. When the water level becomes lower than the TAF, high-temperature unsaturated vapor dries the
 431 chamber, and the water level Z Ref in the pipe connected to the reference condensing water chamber falls from
 432 the reference height L 1 . Accordingly, the measured apparent water level is displayed higher than the actual one
 433 Z F .

434 12 b) Response of TEPCO after the Tsunami Attack

435 TEPCO released a report [25] that described the actions undertaken by TEPCO based on the plant data measured
 436 immediately after the accident. Although this report [25] was published on June 18, 2011, later than the report
 437 on May 23 [3], it is believed that the report describes the situation of the NPP immediately after the accident.
 438 The facts related to the ICs are summarized as follows:

439 March 11, 2011 14:46: The Great East Japan Earthquake occurred. An automatic reactor scram occurred.

440 14:47: Automatic startup of emergency diesel generators occurred.

441 14:52: The ICs of Unit 1 were confirmed to have started automatically.

442 Because the reactor water level was at the normal level, it was decided that the HPCI will be activated when
 443 the reactor water level drops, and the reactor pressure will be controlled by the IC. Around 15:50: The DC power
 444 supply for measurement was lost, and the reactor water level became unknown.

445 We started collecting batteries and cables from companies in the NPP. We brought them to the central control
 446 room, checked the drawings, and started connecting them to the instrument panel in the Unit 1/2 central control
 447 room.

448 In the central control room, the indicator lamps of the return piping isolation valve (MO-3A) and supply
 449 piping isolation valve (MO-2A) were observed to be ON, probably owing to the temporary restoration of the DC
 450 power supply. When we checked the status, we determined that these valves were closed.

451 13 18:18:

452 The return piping isolation valve (MO-3A) and supply piping isolation valve (MO-2A) of the IC were opened,
 453 and steam generation was confirmed. 18:25: The return pipe isolation valve (MO-3A) was closed.

454 14 21:19:

455 The water level in Unit 1 was determined as TAF +200 mm.

456 15 21:30:

457 The return piping isolation valve (MO-3A) was opened, and steam generation was confirmed.

458 16 c) Original Records of Accident and Plant Parameters

459 The Nuclear and Industrial Safety Agency (NISA) released documents from TEPCO [26]. In this document,
 460 original faxes and plant parameters at the time of the accident were included. We examined the large amount of
 461 available original data to investigate the accident.

464 As shown in Fig. 6, there is a description stating "Water supply to IC (A) tank by fire pump" (water is supplying
465 to the resaviour tank of IC(A) by a dieseldriven fire pump(D/D FP) system) in the original plant parameter at
466 00:30 on March 12. Thus, the D/D FP system shown in Fig. ?? may have been supplying cooling water to IC-A
467 at this time. If that is the case, it is highly likely that the water supply stopped before 04:15, because "Water
468 supply to IC(A) tank is suspending" was reported at 04:15.It is possible that the water supply continued until
469 the IC was shut down.

470 TEPCO considered that the IC was not functional [6], because the so called "fail-safe system" worked after
471 the tsunami attack and all valves connecting the RPV and ICs were shut down. TEPCO measured the amount
472 of water in the IC tank long after the accident [3], and there was sufficient water in the tank. The water volume
473 in the reservoir tanks of ICs measured after the accident was in good agreement with the volume of consumed
474 water that was calculated based on the nonfunctional IC. According to the description in Fig. 6, the amount of
475 cooling water in the tank of IC-A based on the assumption by TEPCO that there was no water supply may have
476 been a coincidence.

477 In the original list of plant parameters, recorded at 21:30, there is a record that "The IC is in operation."

478 This implies that the IC was in operation at the latest at 20:30. There is another record in the list of plant
479 parameters recorded at 22:30 that the IC was in operation ("pressure decreased at 21:30. 3A valve opened").
480 These two records contradict each other. From the fact that the IC was in operation as shown in Fig. 6, and
481 from the eyewitness testimony confirming that it is highly likely that the IC was operating as initially reported
482 in the accident.

483 The Investigation Committee of the Government of Japan [4] concluded that the ICs did not function after the
484 tsunami attack, because as soon as the DC power was off, the AC MOVs were closed by the "failsafe" sequence.
485 The Committee also accused that the Director of the Fukushima Daiichi NPP was not aware that the IC had
486 stopped, and that this misunderstanding caused the accident to be more serious. It would have been difficult to
487 believe that the IC was shut down when the central control room reported that the IC was operating and there
488 were various eyewitness reports. In addition, the Committee stated that there was no water supply to the IC.
489 This contradicts the records at the time of the accident, as shown in Fig. 6. ??, it implies that the operators
490 supplied water to the IC tank at this point. This record does not contradict the IC water supply record in Fig.
491 6. The Investigation Committee of the Government of Japan [4] ignored all these records. These descriptions in
492 the white board imply that the restart of the IC was before 21:30, because it is unlikely that water is supplied
493 before the IC starts. Accordingly we assumed that the IC was restarted at 20:30.

494 At the initial stages of the accident, TEPCO reported [25] that the IC was operational after the tsunami attack
495 at 15:36 on March 11, 2011. And steam ejection was observed from the IC when the IC was restarted at 18:18,
496 and 21:30. However, TEPCO assumed that the IC did not function after the tsunami attack in their report [6].
497 They ignored the observed steam ejection at 18:18 and 21:30. They also ignored that water was supplied to the
498 reservoir tank of IC-A at 21:35.

499 The record on the white board indicates that "18:18 IC(A) 2A, 3A open. Steam generation confirmed" (IC(A)
500 MOV-2A and 3A was opened at 18:18, and steam generation was confirmed),"18:25 IC(A) 3A closed" (IC(A)
501 MOV-3A was closed at 18:25) and "21:30 IC(A) 3A open"(IC(A) MOV-3A was opened at 21:30), and "IC(A)
502 steam generation." These records are in accordance with the actions of TEPCO immediately after the
503 accident [25], as described in the previous section b.

504 According to a recent investigation [19], AC power system A became nonfunctional at 15:36:59 on March 11,
505 2011, and the other line was nonfunctional; a few minutes later. As shown in the previous section b, the DC
506 power was lost at approximately 15:50. The ACoperated valve requires approximately 20 s to closefully, and the
507 DC-operated valve requires approximately 15 s. The fail-safe system is activated when the DC power is lost,
508 and the AC-driven motor valves, MOV-1A, MOV-4A, MOV-1B, and MOV-4B, are automatically closed. It is
509 unlikely that the AC-driven motor valves,MOV-1A and MOV-4A,wereclosed by the fail-safe system.

510 Long after the accident, TEPCO investigated the valve positions of MOV-1A and MOV-4A to determine if
511 they were fully closed. The AC power in the NPP was recovered between March 20 and March 24, 2011. It is
512 possible that these AC MOVs were closed by the failsafe signal when the AC power was recovered. As shown in
513 the previous section b, the operators collected batteries and attempted to operate the DC-driven motor valves
514 MOV-3A and MOV-2A. It is highly possible that the valves of the IC were working at the time. 8. We consider
515 the time when the IC was restarted to be 20:30 on March 11 rather than 21:30, as reported in the initial report
516 by TEPCO [26], because there is a record that the IC was working at 20:30 in Fig. 6. We think the rupture
517 in the PCV of Unit 3 occurred at 09:05 on March 13, 2011 [17], which differs from the estimation presented by
518 TEPCO [6].

519 There were two reactor water level meters in the RPV, and their data show different values. The water level
520 was almost constant above the TAF from 21:30 on March 11 to 06:30 on March 12. As shown in the previous
521 section b, the reactor water level meter shows the correct value when the water level is above the TAF. The
522 data may not be accurate, but the discrepancies must be explained reasonably. TEPCO explained in the report

523 on June 20, 2012, that "Therefore, water levels measured after core damage are assumed to be unreliable, while
524 water levels taken via analysis are assumed to be closer to those in reality" [6].

525 The radiation measurement instruments located at various points in the NPP were working independently
526 without the effect of the station blackout; hence, the data and measured times are correct. The data on radiation
527 intensity have to be rationally explained based on the actual occurrences inside Unit 1 in reality.

528 We attempted to construct an accident scenario that explains all the data in Fig. 8, and to determine the
529 actual occurrences in Unit 1 during the accident.

530 18 d) Behavior of Valves and the Water Reservoir of IC

531 When the earthquake occurred, the reactors stopped owing to reactor scram, and the ICs started automatically.
532 Then, the operators stopped IC-B, and IC-A was intermittently operated to maintain the temperature decrease
533 within 55 °C/h or 100 °F/h. MOV-3 of system A was closed when the tsunami arrived.

534 TEPCO [6] and the Investigation Committee on the Accident at the Fukushima Nuclear Power Stations [4]
535 reported that the "fail-safe system" closed all valves connected to the ICs, and that they did not work after the
536 tsunami. Conversely, TEPCO [13] reported that the AC power shut down occurred at 15:36:59, immediately
537 after the tsunami attack. The DC power is estimated to have been active until at least 15:50 [25]. The "fail-safe
538 system" activates when the DC power goes off. These facts imply that the AC MOVs, i.e., MOV-1 and MOV-4,
539 may have been fully open owing to the AC power blackout at the early stage of the accident. This fact was
540 indicated by the author [HTC Rep.26.2, 2013/03/03], [9]. The NRA [19] indicated that MOV-1 and MOV-4
541 may have been open when the tsunami attacked. The operators attempted to operate IC-A by connecting DC
542 batteries for automobiles. If the DC MOVs were open, it is highly possible that IC-A was operational after the
543 tsunami struck.

544 TEPCO reported that the amount of water remaining in the reservoir tank of IC-A agreed with the The water
545 injection to the reservoir tank, and the report of several eyewitnesses (TEPCO operators and workers), who
546 saw steam ejection from the IC, were ignored in the Investigation Committee report on the "Accident at the
547 Fukushima Nuclear Power Stations" [24]. TEPCO also ignored evidence that steam ejection was observed by
548 the workers [25] at 21:30 on March 11. It was also reported in the original plant parameter data that the IC was
549 functional [26]. These facts were ignored in the report of the Investigation Committee [24].

550 TEPCO claims that the increase in radiation dose in the R/B at 21:51 is an evidence of the early meltdown
551 of the RPV because the IC was not working after the tsunami. However, the present analysis shows that the
552 increase in radiation can be explained by an accident scenario, assuming that the IC was working after the
553 tsunami. Furthermore, the behavior of the water level meters can also be reproduced by an accident scenario
554 where the IC was working [HTC Rep.32.2, 2014/03/05].

555 19 IV.

556 20 Proposed Accident Scenario

557 In the present accident scenario, we assumed that the IC was, to a certain extent, functional after the station
558 blackout, and the estimated breakdown of the RPV occurred considerably later than the estimation presented
559 by TEPCO. Moreover, we constructed a detailed thermodynamic model to describe the equilibrium state of the
560 RPV and PCV in the NPP. We determined that the measured data and original records are well described by
561 the simulation using the thermodynamic model. Our simulation program is relatively small and operated on
562 Microsoft Excel. It can be used to calculate one set of accident scenarios within a few seconds, and related
563 diagrams are promptly displayed.

564 In the previous analysis of Unit 1 [HTC Rep.26.1 2013/02/10], [9], we constructed an accident scenario where
565 IC-A was functional after the tsunami attack, and a small leak through a rupture with the equivalent estimated
566 water volume of IC-A if it was not functional after the tsunami. The NISA disclosed the accident data published
567 by TEPCO, where the faxes and original data of plant parameters of reactors were listed [26]. The plant
568 parameter report at 00:30 on March 12 described that the water was injecting into the reservoir tank of the a
569 D/D FP. According to this evidence, IC-A may have been working at that time. The IC may have stopped before
570 04:45 on March 12 because there was evidence that the water injection to reservoir tank IC-A is suspending
571 at 4:45, in the original plant parameters report, as shown in Fig. 7. From the previously mentioned data and
572 evidence, it is highly likely that IC-A was functional after the tsunami attack and stopped before 4:45 on March
573 12. IC-A. As shown in Fig. 6 The NRA analyzed the pressure data from the PCV before the tsunami attack
574 and concluded that the RPV leak did not occur because of the earthquake [11]. We compared the measured
575 data of PCV pressure and the pressure estimation according to the previous accident scenario [9], which assumed
576 an early leakage in the RPV. The previous pressure estimation overestimated the measured data; however, the
577 previous scenario was able describe the rest of the measured pressure data except for the PCV pressure before
578 the tsunami attack.

579 Based on this finding, we proposed a new accident scenario in which a small leakage occurred at a safety valve
580 (SV) of the RPV at 20:26 on March 11, and a large leakage occurred at 06:20 on March 12 at another SV [HTC
581 Rep.35.1, 2015/03/03]. The other scenario is similar to the previous one [9].

In the accident scenario of the present study, it is assumed that the RPV ruptured at 20:26 on March 11, just before IC-A was restarted at 20:30. According to the previous report [9], the water level was below the TAF, and it is expected that high-temperature vapor accumulated at the top of the RPV because the IC stopped at that time. It is also estimated that the abrupt increase in vapor pressure in the RPV may have caused a vapor ejection through an SV whose operating pressure was higher than the SRVs. The SV ejects the steam directly into the PCV or D/W, whereas SRVs eject the steam to the water in the S/C. This discharge of high-temperature vapor from the SV may cause a failure of the SV and create a continuous leak. We assumed that the leak occurred through a rupture with an approximate diameter $d_{RPV} = 1.7$ cm to adjust for the measured PCV pressure data.

The remaining aspects of the accident scenario are similar to the previous one [9]. The present accident scenario is as follows:

1. IC-A was operated manually from 18:18 to 18:25 on March 11.
2. A small RPV leak occurred at 20:26. It is suspected that the position of the leak may have been at a SV.
3. IC-A started again at 20:30 according to the original records [26] and Fig. 6. It is estimated to have stopped at approximately 03:00 on March 12.
4. The PCV leak occurred at 03:30 in the lower part of the PCV. This caused an increase in the radiation dose at 04:00 at the main gate of the NPP.
5. A large leak from the RPV occurred at 06:20, probably from an SV, and it caused a further increase in the PCV rupture at 06:23.
6. The RPV ruptured again at 16:00 at the bottom of the RPV owing to drying out of the RPV.

The details of the accident scenario are listed in Table 2. It should be noted that the estimated areas where rupture occurred in the PCV between 06:23 and 09:00 on March 12 were adjusted to satisfy the measured pressure data. The assumption of phase equilibrium was not satisfied at that time, because the water level was lower than the TAF and the water vapor was not saturated steam.

The water injection rates to the RPV are smaller than those reported by TEPCO. A recent report by TEPCO mentioned that all injected water may not have reached the RPV because there was a bypass in the injection line. It is also noted that the initial water injection at approximately 04:00 on March 12 is incorrect data and can be corrected for good reasons to derive a more truthful accident scenario. Furthermore, by considering the new data, such as the progress of the internal investigation in the reactor, it is possible to estimate the accident even closer to the truth. It is possible to derive accident scenarios that are closer to the truth by correcting erroneous data for appropriate reasons.

Nevertheless, there are still several inconsistencies and unclear points in the present accident scenario listed in Table 2. For example, the restart time of the IC is assumed to be 20:30, which is one hour earlier than the generally accepted restart time. In addition, the PCV destruction times are complicated in the scenario listed in Table 2; however, the scenario in the previous report is simpler and more consistent with the radiation intensity data. This is because the analytical model used in this study assumes vapor-liquid equilibrium in the RPV and PCV; therefore, transient phenomena cannot be described.

Estimation of the rupture location and time on the RPV and PCV, which will be described in subsequent sections, are not in the realm of speculation. However, it is also true that the accident scenario described in Table 2 can explain many of the measured data and events that occurred so far, as will be explained subsequently.

V.

21 Analysis Model

Figure ?? shows the construction diagram of Unit 1 and its physical model for thermo-fluid analysis of the accident scenario. Figure ?? describes the status of Unit 1 as of 12:00 on March 13, 2011, when the RPV and PCV ruptured; moreover, the explosion due to the accumulation of hydrogen at the top portion of the R/B occurred at 15:36 on March 12.

22 a) Analysis Model of RPV and PCV

The physical model in Fig. ?? is simplified to a thermodynamic model, as shown in Fig. ??0. The RPV and PCV are simplified vessels that contain vapor and liquid water at saturation conditions. The thermodynamic model of the saturation conditions is similar to the previous models [8], [9]. This model is based on the conservation of mass and energy in the vessels, and the assumption of the phase equilibrium of water and vapor in the vessels. Details of the model were described in the previous report [8].

, [kg/s] inj RPV SRV m m m ? ? ? , [W] FUEL IC Q Q ? ? ? respectively.

The differential temperature changes in the RPV and PCV are expressed as follows, assuming the phase equilibrium between the water and the vapor [8].

$$m_m h_m + m_v h_v + Q_{in} - m_c h_c - m_e h_e = \dot{m}_v h_v - \dot{m}_m h_m + \dot{m}_c h_c - \dot{m}_e h_e + \dot{Q}_{in} - \dot{Q}_{out} \quad (1)$$

$$m_m h_m + m_v h_v + Q_{in} - m_c h_c - m_e h_e = \dot{m}_v h_v - \dot{m}_m h_m + \dot{m}_c h_c - \dot{m}_e h_e + \dot{Q}_{in} - \dot{Q}_{out} \quad (2)$$

Here, h , v , and c_p represent the enthalpy, specific volume, and specific heat at constant pressure, respectively. The notations "m" and "v" express the states of water and vapor at the equilibrium condition, respectively. The model assumes that the temperature in the RPV and PCV is uniform. Hence, this model cannot describe the phenomena when the water level is below the TAF and the vessel is filled with superheated vapor.

As shown in the previous report [7], the time history of the decay heat in Unit 1 can be estimated relatively accurately. Because the decay heat is released from the ruptured vessel as steam, the mass flow rate of the steam can be estimated. Assuming the rupture cross section, the pressure difference between the inside and outside of the vessel can be estimated using Bernoulli's equation. Thus, the relationship between the steam flow rate, fracture aperture area, and pressure difference inside and outside the vessel is expressed by the following equation [27]:

$$Q = C_d A \sqrt{2 \rho (p_i - p_o)} \quad (3)$$

where Q [m³/s] is the mass flow rate, p_i [Pa] is the pressure inside the vessel, p_o [Pa] is the pressure outside the vessel, and C_d is the discharge coefficient. When the pressure difference becomes large, the flow rate through the vessel opening reaches the speed of sound. The flow rate at that time is expressed by the following equation [24]:

$$Q = C_d A \sqrt{2 \rho p_i} \left(\frac{p_o}{p_i} \right)^{\frac{1}{\gamma}} \left(\frac{p_i}{p_o} \right)^{\frac{\gamma-1}{\gamma}} \quad (4)$$

where a [m/s] is the speed of sound, γ is the specific heat ratio of the vapor, and a value of 1.34 for saturated vapor at 100°C was used as an approximation. The subscript 0 indicates the value in the vessel, and * indicates the state at the velocity of sound. The flow coefficient of the orifice was assumed to be the same as that of a subsonic orifice at the speed of sound. These equations can be used to estimate the steam flow from the RPV to the PCV or from the PCV to the external environment.

When the RPV ruptures and the vapor is ejected to the vapor-phase space of the PCV or D/W, the temperature varies between the D/W and the S/C. In this case, the vapor in the RPV is ejected to the PCV in the adiabatic condition. Using the adiabatic expansion model adopted in a previous report [7], [9], the pressure and temperature changes in differential time dt is expressed as follows:

$$\frac{1}{\rho} \frac{d\rho}{dt} + \frac{1}{T} \frac{dT}{dt} = -\frac{1}{\gamma} \frac{1}{p} \frac{dp}{dt} \quad (5)$$

Volume Xx XI Issue I V ersion I Global Journal of Researches in Engineering () +d d D W D W D W D W D W D W p p V V p V ? ? ? + = ? ? ? ? (8)

Where, the notations follow the ones in Fig. ??0. Note that the analysis according to the adiabatic expansion model does not give an accurate estimation when the water level is below the TAF, and the RPV is filled with superheated vapor. This is because the present model assumes that the ejected vapor is at the saturation condition.

Fig. ??1: Comparison with measured plant parameters of Unit 2 and analysis using the thermodynamic model [8] To demonstrate the accuracy of the present thermodynamic model when compared to measured data of the accident, a comparison of the present analysis with the measured data of Unit 2 is shown in Fig. ??1. Our accident scenario of Unit 2 [8] is similar to that of TEPCO. And our analysis result shows better agreement than that of TEPCO.

TEPCO used a large computer simulation code called MAAP. It is a large simulation program to analyze the transient phenomena during a nuclear plant accident; however, it requires a long time to simulate an accident scenario. The present simulation can be conducted using Microsoft Excel, and it requires only a few seconds to simulate one accident scenario. The program can also express appropriate diagrams, as shown in Fig. ??1, to examine the analysis results. Accordingly, our simulation program can provide a large number of accident scenarios to obtain good agreement with the data measured during the accident.

23 b) Analysis of Reactor Water Level Meter

TEPCO constructed a scenario of IC shutdown and early meltdown of the reactor core, claiming that the indicated value of the water level meter in Unit 1 is completely unreliable [6]. The Government Accident Independent Investigation Commission [4] also qualitatively stated the reasons why the water level gauges were not working properly based on the report by TEPCO [6]. However, they did not quantitatively evaluate the readings of the water level meters at that time, and stated that the indicated values of the water level meters were completely wrong. The later report submitted by TEPCO [16] suggests that the indicated values of the water level meters at that time may have contained some information.

We used the model illustrated in Fig. 5, and try to reproduce the water level meter measurements, as shown in Fig. 8. As described in Section III a, the water level meter gives the correct value when the water level Volume Xx XI Issue I V ersion I Global Journal of Researches in Engineering () F © 2021 Global Journals in the RPV is higher than the TAF because of the structure of the reference condensing water chamber. The reference water level Z_{Ref} is L_1 , as shown in Fig. 5, when Z_F is above the TAF. When the water level Z_F is lower than the TAF, the relationship between the apparent water level Z_{Level} and the actual water level Z_F is expressed by the following equation:

$$Z_{Level} = Z_F + \frac{H_F}{\rho g} \quad (9)$$

When boiling occurs in the fuel assembly, the water head of the fuel assembly H_F and the apparent water level H_W may be different. Thus, when water boils in the vertical channel, the apparent water level H_W increases owing to the bubbles. Even if the water level H_F falls below the TAF level, the reference water level Z_{Ref} is considered to maintain the reference level of $L_1 = 5.11$ m as long as the apparent water level H_W in the fuel assembly channel reaches the TAF, as shown in Fig. 5.

When the water level in the channel drops below the TAF, the reference water level Z_{Ref} in the reference pipe starts to decrease. The speed of the water level reduction depends on the temperature distribution in the

703 RPV and the pipeline layout. In this study, it is assumed that the reference surface water level Z Ref decreases
704 at the same rate as the RPV water level Z F decreases. It is also assumed that once the reference surface water
705 level decreases, it will not return to the original level owing to the vertical temperature distribution in the RPV.
706 In addition, it is assumed that the lowered reference water level will be maintained while the IC is in operation.

707 It was assumed that for the water level meter of system B, the water level at the reference surface was suspended
708 at 3.0 m above the TAF when the IC was restarted at 20:30, and the water level remained unchanged until the
709 IC was stopped at 3:00. At the water level meter in system A, the reference surface water level dropped again
710 at 23:30 and reached 2.5 m above the TAF, and then the water level remained constant until the IC stopped.
711 To validate the above-mentioned analysis model and the assumptions, a comparison of the measured water level
712 and our analysis is shown in Fig. 12. The calculated reactor water level was obtained from the thermodynamic
713 model using the accident scenario listed in Table 2.

714 With the above-mentioned assumptions, the water level meter indication at the accident can be reproduced.
715 However, the validity of the speed at which the water level lowered in the reference level meter when the water
716 level fell below the TAF is not clear; however, the above-mentioned assumptions can explain the data obtained
717 from the water level meters at that time. TEPCO reported that there is horizontal piping of the reference
718 level meter, and that system B is approximately 3 m longer than system A. At this stage, Volume Xx XI Issue
719 I V ersion I Global Journal of Researches in Engineering () F the details of the water level piping have not
720 been disclosed. If there is a type of horizontal piping, such as a piping around TAF +3.0m and TAF +2.5m,
721 this hypothesis can be proven. At present, as the location of the piping is unknown, this assessment is only a
722 speculation.

723 After the IC was shut down at 03:00 on March 12 the reference water level was assumed to decrease at the
724 same rate as the water level in the RPV. When the RPV ruptured at 06:20 and the pressure decreased rapidly,
725 the reactor water level decreased rapidly. The present estimation with these assumptions describes the measured
726 water level after the RPV rupture.

727 As shown in Fig. 5, when the reference water level is below TAF -2.04 m, the water level in the pipe Z Ref
728 does not decrease anymore because the pipe goes outside the PCV. Further, the apparent water level in the fuel
729 region Z F does not decrease because the pipes of the water level in the RPV also go out of the PCV at TAF
730 -8.94 m. Therefore, the apparent water level Z Level becomes constant after 14:20. This estimation is in good
731 agreement with the measured apparent water level.

732 TEPCO attempted to reproduce the measurement of reactor water level meters and claimed that they
733 succeeded in reproducing the data with the accident scenario simulated by TEPCO [16] in the attachments
734 1-6. The scenario simulated by TEPCO assumed that the water level became the BAF at 19:40 on March 11,
735 which is significantly earlier than our estimation. When we examined the data in the attachment 1-6 [16], the
736 "calculated variable leg water level above PCV penetration" in the attachment could not be understood. TEPCO
737 did not explain the calculation procedure.

738 24 VI.

739 25 Results and Discussion a) Pressures in PCV

740 Figure 13 shows the pressure simulations in the RPV and PCV according to the present accident scenario, which
741 is listed in Table 2. The measured data of pressure in the D/W, S/C, and RPV, as shown in Fig. 8, were
742 compared with the present simulation. The radiation dose at the main gate of the NPP is also depicted in Fig.
743 13. The pressure estimation of the PCV, i.e., the S/C and D/W, agrees well with the measured data, except for
744 the measurement at 01:05 on March 12. This datum did not appear in the original data reported at that time
745 [26]. The areas where rupture occurred in the PCV from 06:23 to 09:00 on March 12 were set to satisfy the
746 measured data, because the assumption of phase equilibrium is not satisfied when the water level is lower than
747 the TAF. Furthermore, superheated vapor was ejected from the RPV to D/W at that time.

748 We suspect that when the water level became lower than the TAF at 20:26 on March 11, the temperature of
749 the steam increased and the zirconium sheath of the fuel rods reacted with the hightemperature steam, resulting
750 in the generation of hightemperature hydrogen gas. This high-temperature steam and hydrogen gas may leak
751 from the RPV; consequently, the pressure in the PCV starts to increase. In the present accident scenario, we
752 assumed that the RPV had a small leak at 20:26.

753 This accident scenario explains that the reason for the increase in the radiation level in the R/B at 21:51,
754 because the leaked contaminated gas from the RPV was stored in the PCV, resulting in an increase in the
755 radiation in the R/B at that time. Then, the PCV ruptured at around 03:30 on March 12 owing to the high
756 pressure. At this stage, the IC had stopped, and the water level was lower than that at 20:26 on March 11. The
757 ruptured area was estimated to be of an equivalent diameter of 1.7cmRPV $d =$.

758 The ruptured area increased at 06:23 owing to the steam ejection from the RPV that ruptured at 06:20. The
759 real rupture area of the PCV cannot be estimated because the superheated vapor cannot be estimated using
760 Eqs. (4) and (5). When water was injected into the RPV, the ejected steam became saturated again. According
761 to the estimation at 08:00, the rupture diameter was approximately 8 cm, which is in good agreement with our
762 early estimation [9].

763 The pressure after 10:26 decreased owing to the venting of the PCV. As listed in Table 2, the apparent rupture

764 area increased owing to the vent motion of the PCV and the area returned to the previous value when the venting
765 valve was closed. Note that the rupture area did not change with the hydrogen explosion at 15:36. This indicates
766 that the rupture position was in the lower part of the PCV, as specified by the author [7]. This was also proved
767 by TEPCO [13].

768 The radiation intensity increased 12 times between 04:00 and 04:40, and it also increased between 05:10 and
769 06:30. These increases in radiation dose agree with the present estimation of the PCV rupture times of 03:30 and
770 06:23. The radiation dose increased in the R/B at 21:51 on March 11; consequently, entering the building was
771 prohibited. The radiation dose at the main gate did not increase at that time, as shown in Fig. 13. This implies
772 that the contaminated gases that leaked from the RPV at 20:26 into the PCV may not have leaked into the
773 environment. The water level of the RPV was under the TAF from the present estimation, and the contaminated
774 vapor in the RPV may have leaked to the PCV after 20:26.

775 26 b) Pressure Values in RPV

776 The pressure estimation of the RPV by the present accident scenario is also shown in Fig. 13. This estimation
777 assumes that IC-A was working between the times of 18:18 and 18:25. It also assumes that the IC was restarted
778 at 20:30 according to the original data presented by TEPCO [26] and as shown in Fig. 6. This analysis assumes
779 that the IC was nonfunctional at approximately 03:00 on March 11. It is suspected that the hydrogen produced by
780 the zirconium-water-vapor reaction accumulated in the RPV, and the accumulated gas stopped the condensation
781 of vapor in the IC.

782 This estimation of the time at which the IC stopped functioning is significantly later than that estimated by
783 TEPCO [16]. The report published by TEPCO states that "When compared with the progression in the IC
784 continuous operation after 18:25, the continued IC operation delayed the RPV damage and led to less erosion
785 of the containment vessel concrete. But in the overall progression of the accident, it would be quite likely that
786 there was only a minor difference from what actually occurred in Unit-1." TEPCO estimated that the IC became
787 nonfunctional because the accumulated hydrogen deteriorated the condensation ability in the IC in the early
788 stage of the accident.

789 The estimation presented by TEPCO may be possible when the condensation heat transfer in the IC is a
790 natural convection type of heat transfer such as the condenser in Fig. ???. The condenser in the power plant
791 condenses the vapor outside the heat transfer pipe and cooling water is circulated in the pipe. However, in the
792 case of the IC, the condensing steam flows in the pipe, and the cooling water is boiling outside the pipe. As
793 shown in Fig. ??, the ICs were placed at high positions. The condensed water in the IC is subjected to a large
794 suction head owing to the large difference in height between the IC and the entrance of the condensed water
795 at the RPV. In this case, we consider that the forced convection condensation may have continued after the
796 generation of hydrogen gas. Hence, we estimated that the IC became nonfunctional at approximately 03:00 on
797 March 12.

798 According to the discussion in a previous report [9], the cooling performance of the IC was significantly greater
799 than the decay heat generated when the operators restarted IC-A at 18:18, which was 3.5 h after the scram. The
800 pressure quickly decreased after the restart of the IC. The pressure increased after IC-A stopped manually at
801 18:25; then, the SRV blew steam to the S/C and the water level in the RPV decreased. We Volume Xx XI Issue
802 I V ersion I Global Journal of Researches in Engineering () F assumed that the IC restarted at 20:30. At that
803 time the water level was below the TAF, as shown in Fig. 12.

804 It is extrapolated that vapor circulation from the operating IC may have maintained the fuel rods at relatively
805 low temperatures. However, the temperature becomes significantly high when the vapor circulation stops owing
806 to the failure of the IC. According to this discussion, certain fuel rods may have been at a high temperature at
807 20:26 and the high-temperature vapor would have accumulated at the top of the RPV. It can be expected that
808 the temperature of certain rods increased, and a reaction occurred between the zirconium and the water vapor.
809 This abrupt increase in temperature and the gas generation may have caused a small leak on the RPV at 20:26.

810 The temperature in the RPV may have decreased after the IC started again at 20:30 and the fuel temperature
811 at TAF may have stayed at a relatively low temperature until the IC stopped at 03:00 on March 12. Then, the
812 pressure and temperature in the RPV increased promptly and the breakdown of the fuel core may have started.
813 In this case, the pressure in the RPV is expected to be significantly higher than that estimated in Fig. 13 because
814 the estimated pressure assumes phase equilibrium of the water vapor.

815 There are only two pressure values that were measured for the RPV after the tsunami attack and before the
816 hydrogen explosion at 15:36 on March 12. When we examined the pressure data at 20:07 on March 11 the original
817 value was in the range of 6.7-7.3 MPa, as shown in Fig. 13. TEPCO adopted the average value in their reports
818 [16]. The pressure at 02:45 on March 12 was 0.901 MPa. TEPCO claimed that this low pressure is an evidence
819 that the IC was not working and the RPV ruptured in the early stage of the accident.

820 The IC had a sufficiently large cooling performance to cool the decay heat just after the scram. The decay
821 heat at 02:45 was 22% of the value that was estimated immediately after the scram [7]. As shown in Fig. 13,
822 the pressure in the RPV decreased quickly and became the measured pressure at 02:45. Thus, it was determined
823 that this pressure decrease in the RPV could be achieved if the IC was working.

824 When the IC stopped at 03:00, the pressure increased significantly quickly. We estimated that the RPV
825 fracture occurred at 6:20 owing to the quick increase in the pressure of the RPV. The blow-in gas from the RPV

826 to the PCV caused the pressure to increase at 06:23. Fig. ???: Estimated water level in the RPV according to
827 the present scenario in comparison with measurements in Fig. 8 and the estimations presented by TEPCO [12].
828 The present estimation shows the water level was lower than the TAF at 20:26 on 11 March, and a small leakage
829 occurred in the RPV. This explains the radiation increase in the reactor building at 21:51. IC-A was restarted
830 at 20:30, and stopped at 03:00 on March 12. We estimate that the RPV ruptured at 06:20; then, the water level
831 reached the bottom and the fuel leaked out at approximately at 16:00.

832 27 Volume

833 28 c) Water Levels in RPV

834 Figure ???: shows the estimated water levels and measured data from reactor water level meters A and B.
835 According to heat transfer analysis of fuel clusters, the water level in the fuel cluster is higher than the water
836 level outside the shroud when the water level becomes lower than the TAF [HTC Rep.26.2, 2013/03/03], [9].

837 The water levels (outside the shroud), as estimated by TEPCO [12], and the estimation that the author derived
838 from the heat transfer model in Section V b and Fig. 12 are also shown in Fig. ???. The upper part of the
839 fuel may have been wet because boiling water inside the fuel cluster expanded owing to the void in the cluster
840 channels. The water level in the cluster channel Z w is also shown in Fig. ???. This can be estimated by the void
841 fraction distribution or quality distribution in the fuel cluster, assuming the cluster is a single pipe with uniform
842 heat flux, as discussed in a previous report [9].

843 When the IC restarted, as discussed above, the vapor circulation from the operating IC may have kept the
844 fuel rods at relatively low temperatures, even if the water level Z W was below the TAF. When the IC stopped,
845 and the water level in the cluster Z w became lower than the TAF, the fuel surface was covered with pure vapor
846 and the wall temperature increased rapidly. The temperature of the steam and the surface of the fuel rod at
847 the TAF can be estimated by the steam generation rate and forced convection in a pipe [9]. The estimated wall
848 temperatures of the fuel rod and steam at the TAF are shown in Fig. ???.

849 The estimated rates of water injection to the RPV are shown in Fig. ???. The injection rates are smaller
850 than the reported values, because there is a possibility that the injected water entered the bypass line, and all
851 water may not reach the RPV. The injection rate was adjusted to satisfy the condition that the reconstructed
852 water level meters in Fig. 12 In the present estimation, the water level started to decrease at 15:59 on March
853 11 as the RPV steam was blown down to the S/C by the SRVs. This behavior agrees with the measured data
854 [13]. The decrease in water level stopped when the operators restarted the IC at 18:18. Then, the water level
855 started decreasing again at 19:14 because the IC was stopped at 18:25. The water level reached the TAF at 19:30.
856 At that time, the fuel cluster at the TAF was still wet because the bubbly flow in the fuel cluster maintained
857 saturation temperature at the fuel surface.

858 When the water level was below the TAF at 20:26, the fuel rods at the TAF dried out and hightemperature
859 steam was ejected to the upper part of the RPV. The pressure and temperature of the steam at that time
860 is expected to be significantly higher than the estimation. Moreover, the zirconium-steam reaction may have
861 occurred at that time. It is suspected that the hightemperature steam was ejected through a SV.

862 When the IC was restarted at 20:30, the water levels in the RPV and fuel cluster were below the TAF. However,
863 it is estimated that the vapor temperature and pressure decreased owing to the circulation of water and vapor
864 through the IC. When the IC was working, stable circulation was maintained until the IC stopped again. This
865 stable water level indicates satisfactory operation of the water level meters, and the measured water level data
866 can be reconstructed as shown in Fig. 12.

867 TEPCO [12] carried out a simulation of the accident at Unit 1 using the simulation program MAAP. TEPCO
868 estimated an early meltdown due to the nonfunctional IC after the tsunami attack. We performed a simulation
869 based on the same accident scenario that was adopted by TEPCO [9] and obtained approximately identical
870 results for the water level in the RPV as obtained by MAAP. However, the water level estimation by TEPCO
871 [12] could not reconstruct the measured water level data [HTC Rep.32.2, 2014/03/05].

872 We estimated that the IC stopped at approximately 03:00 on March 12. Then, the temperature of the fuel
873 increased rapidly, as shown in Fig. ???, and the meltdown started. The water level in the RPV decreased quickly
874 because of decompression boiling due to the abrupt pressure decrease at 06:20. The RPV ruptured owing to the
875 high pressure and high temperature of vapor in the upper part of the RPV at 06:20. The vapor ejected to the
876 PCV caused a rapid increase in the size of the ruptured area of the PCV at 06:23. It should be noted that the
877 present thermodynamic model cannot accurately express the behavior of the RPV when the water level is below
878 the TAF. However, the phenomena that occurred can be qualitatively described by adjusting parameters such as
879 the rupture area.

880 As the pressure in the RPV decreased, water injection started at 08:00, as shown in Fig. ???. At that time,
881 we considered that the thermodynamic equilibrium was somehow maintained owing to the injection of water.
882 The injection rates were smaller than the reported values, because there is a possibility that the injected water
883 entered the bypass line and the entire amount of water may not reach the RPV. The injection rate was adjusted
884 to satisfy the condition that the reconstructed water level meters in Fig. 12 agree with the obtained data.

885 The reactor water level decreased after the RPV ruptured at 06:20, and it became almost zero at approximately
886 16:00. The present accident scenario estimated that the RPV ruptured again at that time. TEPCO estimated

887 that the RPV melted down around 22:00 on March 11. This is significantly earlier than our estimation at around
888 16:00 on March 12. The molten fuel may have spilled out from the bottom of the RPV; however, this scenario
889 estimates that a large portion of Volume Xx XI Issue I V ersion I Global Journal of Researches in Engineering ()
890) F the fuel remains in the RPV to date. The reasons for this estimation are discussed in the subsequent section.

891 29 VII. Prediction of Rupture Times and Positions

892 From the previous discussion, it is possible to explain the measurement data, activity records, and eyewitness
893 testimonies of the workers at that time, if the IC is assumed to be working for a certain period of time after the
894 tsunami attack. The accident scenario listed in Table 2 can explain, to some extent, the pressure data, water
895 levels, and radiation intensities of the RPV and PCV, which were measured at the time of the accident.

896 We estimated that at 20:26 on March 11, a crack with an equivalent diameter of 1.7 cm occurred in the RPV
897 and steam was ejected into the D/W. At 03:30 on March 12, the PCV was damaged and its equivalent diameter
898 was 3.5-3.7 cm. At 06:20, the RPV was damaged and a large amount of steam was ejected into the D/W. The
899 equivalent diameter of the damaged part of the RPV was 7 cm. The water in the RPV ran out and the molten
900 fuel leaked from the bottom of the RPV into the pedestal of the PCV at approximately at 16:00. The time of
901 fuel leakage was significantly later than that presented in the evaluation by TEPCO, and we estimated that a
902 significant fraction of the fuel remained in the RPV. Subsequently, when the water injection stabilized, the cracks
903 at the bottom of the RPV were blocked by water and molten fuel, and steam continued to leak from the cracks
904 at the upper part of the RPV.

905 We estimated the location of the rupture on the PCV [HTC Rep.25.1, 2012/12/26], [9], and we presumed that
906 the location of the rupture was at the bellows that connects the D/W and the S/C. TEPCO examined the interior
907 of the R/B and estimated that the rupture occurred at the bellows near the bottom of the D/W and vacuum
908 breaker tube [13]. This position is considerably close to our estimated position [HTC Rep.25.1, 2012/12/26].

909 Between March 20 and 22, 2011, there was a period of time when the water injection rate into Unit 1 was
910 significantly low. This decrease in water injection resulted in the temperature of the entire reactor reaching
911 approximately 400°C. After March 23, the water injection volume increased and the temperature inside the
912 reactor rapidly dropped. Electric power was restored to the central control room after March 20, and temperature
913 data from various parts of the reactor was finally obtained.

914 By examining the temperature data of each part of the reactor, it is possible to estimate the condition of
915 the reactor after the accident and the damaged parts to a certain extent. However, the exact locations of the
916 temperature sensors and the reactor components are not known at this time. It is important to understand that
917 there are a number of uncertainty factors involved in such estimations. This analysis is based on public data;
918 however, it is expected that there are several unpublished reports that are not available to the author. It is
919 possible that the present estimation may not be accurate when those data become available.

920 In this section, the author attempts to present bold predictions regarding the positions and times of vessel
921 ruptures according to the present accident scenario listed in Table 2. These predictions may change based on
922 different accident scenarios, and the present predictions may not be accurate. However, to contribute to the
923 nuclear reactor accidents in the future, we will attempt to estimate the locations and times of the ruptures in
924 the RPV and PCV without fear of being accused of inaccuracy.

925 30 a) Identification of Temperature Measurement Points

926 TEPCO released the temperature measurement data of each part of the reactor after March 20, 2011, and in the
927 Microsoft Excel format on May 17 [29]. Table 3 lists the "List of plant data collected by the operator during the
928 accident" [30] and the locations and names of the temperature data that were measured immediately after the
929 accident, as estimated from various public data. Based on these data, it is possible to estimate the locations and
930 names of the temperature data measured immediately after the accident. The temperature measurement points
931 of each part of the reactor were estimated and are shown in Figs. 15 and 16.

932 The position of the water supply nozzle is important; however, the exact location is unknown. Further, there
933 is no precise information regarding the location of the temperature sensors of the SV and SRV, and the direction
934 in which the SV blows out the steam. If this information was available, the accuracy of the estimation would
935 increase. 3 and various published data. Therefore, these positions may differ from the actual positions. The
936 numbering of the temperature measurement points shown in Figs. 15 and 16 corresponds to the numbers listed
937 in Table 3.

938 Figure 16(c) describes the estimated locations of the SRV and SV installed in Unit 1. Both valves were installed
939 on the main steam pipe. The steam released from the SRV was condensed with water in the S/C. However, the
940 steam released from the SV was ejected directly to the D/W. Therefore, the pressure in the PCV may rise rapidly
941 when the SV is activated. The pressurerelease setting of the SV is higher than that of the SRV. According to
942 the attachment of the interim report published by ??EPCO [31], the working pressure of the SRV ranges from
943 7.27 to 7.71 MPa, while the working pressure of the SV ranges from 8.51 to 8.62 MPa; consequently, the SV is
944 not activated under normal operating conditions. However, the SV may be activated when the water level in the
945 RPV drops below the TAF and the pressure increases rapidly, as is the case when the steam-zirconium reaction
946 occurs. As mentioned above, the amount of water injected into Unit 1 was significantly reduced from March 20

947 to 22, and the temperature in various parts of the reactor reached 400°C. Then, the amount of water injected into
948 the reactor core increased, resulting in a rapid decrease in the temperature inside the reactor. Figure 17 shows
949 the temperature changes in each part of the reactor that could be measured after March 20. The temperature
950 measurement points are listed in Table 3 and illustrated in Figs. 15 and Figure 17 shows that the temperature of
951 each part of the reactor increased and became almost uniform owing to the extreme decrease in water injection
952 from March 20 to 22. After the water injection rate was stabilized in April, the temperature of each part of the
953 reactor gradually decreased with the decrease in the decay heat.

954 First, let us compare the temperature measurement position in Fig. 15 with the temperature change in Fig.
955 17(a). It should be noted that the temperature at the bottom of the RPV (TC27) decreased simultaneously with
956 the water injection and became equal to the saturation temperature of the D/W. The temperature of the control
957 rod drive housing in the PCV, which is called the control rod drive (CRD), (TC28 and TC29) was also at the
958 saturation temperature of the D/W. Conversely, the end of the water supply nozzle N4B (TC22) and SV 203-4A
959 (TC30) remained hot and their temperatures were higher than the RPV saturation temperature. The end of the
960 feed water nozzle N4C (TC24) was at the same temperature as the bottom of the reactor. This suggests that
961 the water supply was coming from here, and the temperature was low.

962 Let us assume that most of the fuel rods have melted out of the RPV into the PCV and accumulated in
963 the pedestal at the bottom of the PCV, as TEPCO estimates. Water injection would flow from the feed water
964 nozzles into the RPV and flow out of the bottom of the RPV to cool the fuel deposited in the PCV. Therefore, the
965 temperature of the D/W with the heat source should be higher than the temperature inside the RPV. However,
966 the measurement result indicated the opposite. Furthermore, the temperature inside the D/W (TC39) was lower
967 than the saturation temperature of the D/W. The phenomena estimated by TEPCO is unlikely because the D/W
968 is filled with high-temperature vapor when most of the fuel is discharged into the PCV.

969 By assuming the accident scenario of this report, as listed in Table 2, the injected water leaked out from
970 the hole at the bottom of the RPV, which was formed at approximately at 16:00 on March 12. Conversely, the
971 superheated steam generated by the fuel in the RPV leaked out from the crack in the gas phase. These phenomena
972 explain the temperature changes shown in Fig. 17(a). The fractures in the RPV were formed at approximately
973 at 10:26 on March 11 and at 06:20 on March 12. As the water injection into the RPV has been stable since
974 March 23, it is presumed that the water that saturated in the RPV leaked out from the lower part of the RPV.
975 The water caused the lower part of the RPV and the D/W of the RPV to have homogeneous temperatures.

976 Next, the thermometer arrangement in Fig. 16(c) is compared with the reactor temperature data in Fig.
977 17(b). If the SV (203-4A), which is connected to the main steam pipe of system B, was damaged and continued
978 to discharge steam, it can be explained that the thermometer at the end of the feed water nozzle N4B (TC22)
979 and the temperature data of SV 203-4A (TC30), which is installed near the main steam pipe of system B in the
980 RPV, showed prominently high temperatures.

981 Conversely, the temperature of the end of the feed water nozzle N4C (TC24) in Fig. 17(a) is cold at the same
982 time, when the water injection restarted. This suggests that water injection to the core was performed through
983 nozzles N4C and N4B immediately after the accident; however, the authors do not have detailed data regarding
984 this. The inner thermometer (TC23) of nozzle N4B is also at a low temperature. As the detailed locations of the
985 thermometers are not known, further investigation is required to determine these phenomena.

986 While considering the SV and SRV temperatures, SRV203-3B (TC34) near SV203-4A (TC30) showed a high
987 temperature. One possibility is that the steam that leaked from SV203-4A hit the temperature measurement
988 point of SRV203-3B, and TC30 recorded a high temperature. Conversely, the high-temperature steam have been
989 released from the SRV to the S/C at approximately 06:20 on March 12. It is also possible that the steam damaged
990 the valve seat of SRV203-3B at that time, and the steam continued to leak from the SRV after March 23.

991 As for the SVs, SV203-4C (TC31) recorded the second-highest temperature after SV203-4A. If the steam that
992 leaked at 20:26 on March 11 was caused by the valve seat damage of this SV, the temperature change of TC31
993 can be understood. The SRV (SRV203-3B) showed temperatures higher than the saturation temperature of the
994 D/W. It is possible that the valve seat of the SRV was damaged by the hot steam leak at 06:20 on March 12, as
995 shown in Figure ??4, and the leak continued.

996 It will be a long time before the SV and SRV are retrieved and inspected; therefore, this assumption cannot
997 be clarified until further investigations are performed. It may not be possible to ever identify the locations of the
998 RPV leaks.

999 31 c) Estimation of Fracture Status based on Temperature Data

1000 In the interim report document presented by TEPCO [31], the operating pressures of the SVs and SRVs are shown;
1001 however, the pressure values that are set for the operation of each valve are not stated. Therefore, assuming that
1002 the accident scenario in this report is correct, the estimated valves and estimated operating pressures are listed
1003 in Table 4. According to this accident scenario and Figure 17(b), the pressures set for the operation of SV203-4C
1004 and SV203-4A must be lower than that of SV203-4B for the valve seat of SV203-4C to become stuck at 20:26 on
1005 March 11 owing to the high-temperature steam and for SV203-4A to be damaged at 06:20 on March 12.

1006 **32 Volume Xx XI Issue I V ersion I Global Journal of Re-**
1007 **searches in Engineering () F**

1008 As mentioned earlier, the seat of the SRV (SRV203-3B) may have also become stuck at this time. The temperature
1009 of SRV203-3C increased marginally after the injection of nitrogen; therefore, the operation pressure was estimated
1010 to be lower than SRV203-3A and SRV203-3D. If the estimated value and the actual valve setting operating
1011 pressure are the same, the accuracy of this accident scenario will increase.

1012 According to the estimation in this report, the SVs may have been activated owing to the rapid pressure
1013 increase and dry out of the fuel rods after 20:26 on March 11 and 03:00 on March 12. As shown in Fig. ??4, it is
1014 presumed that the steam stored in the upper part of the vessel was significantly hot when the RPV was destroyed.
1015 At that time, it cannot be excluded that the valve seat and other parts of the SVs were damaged, and the valve
1016 was maintained in an open condition. In general, the maximum operating temperature of the SRV is 302 °C, and
1017 the maximum operating temperature of the other valves are 550 °C. Because zircaloy reacts with steam above a
1018 temperature of 900°C, it is likely that steam at a temperature considerably higher than the maximum operating
1019 temperature passed through the SVs and SRVs. Based on the accident scenario of this report, and considering
1020 Figs. 13 and 14 and the aforementioned discussion, and making a bold prediction, the destruction scenario for
1021 Unit 1 is estimated to be as follows.

1022 1. At approximately 20:26 on March 11, hightemperature steam from the RPV passed through the SV and
1023 circulated into the D/W.As the valve seat of SV203-4C was stuck, the steam blew out through a rupture with an
1024 equivalent diameter of 1.7 cm. 2. The leaked contaminated gas from the RPV was stored in the PCV, resulting
1025 in an increase in the radiation in the R/B at that time. Accordingly, entry to the R/B was prohibited at 21:51.
1026 3. The PCV pressure increased owing to this steam discharge, and at approximately 03:30 on March 12 a crack
1027 with an equivalent diameter of 3.5 cm occurred in the bellows of the vacuum break valve connecting the D/W
1028 and S/C in the lower part of the PCV.

1029 4. The radiation level at the main gate increased after 04:00 due to the contaminated gas that released from
1030 the PCV to the environment. 5. The temperature and pressure of the RPV increased rapidly due to the IC
1031 shutdown at approximately 03:00; moreover, the valve seat of the SV (SV203-4A) was stuck at 06:20, resulting
1032 in a rupture with 7 cm diameter. 6. At approximately at 06:23, the crack at the bottom of the PCV widened or
1033 a new crack appeared. The size of the crack was equivalent to 8 cm in diameter.

1034 There is a possibility that the PCV was damaged again in addition to the crack at the bellows of the vacuum
1035 break valve. 7. The water in the RPV was running out, and the R/B experienced a hydrogen gas explosion at
1036 15:36, resulting in the cessation of water injection. Moreover, at approximately at 16:00, a hole was created at the
1037 bottom of the RPV and the molten fuel was discharged. However, a significant fraction of the fuel is considered
1038 to have remained in the RPV.

1039 For the estimation of the location of the destruction, it is essential to obtain a more detailed structure of the
1040 reactor and accurate information such as the location of the temperature sensors and the location of the SVs and
1041 SRVs. However, this information was not available at the time of writing this report. If this information can be
1042 obtained in the future, it will be possible to estimate the damage location with a higher degree of accuracy. The
1043 estimated failure location may change when the detailed reactor structure becomes known.

1044 To contribute to the internal investigation of the PCV and RPV to be conducted in the future, the status
1045 inside the RPV can be estimated based on the accident scenario in this report. However, this is only a bold
1046 estimation; moreover, it is quite possible that the current accident scenario will be completely different when new
1047 information becomes available. 18 shows the location where the radiation intensity is estimated to be high owing
1048 to this accident scenario. We estimate that the largest leak occurred at the safety valve, SV203-4A (TC30) at
1049 around 06:20. The leaked steam might have been ejected to TC34. Because the SRV valve seat is also considered
1050 to be damaged to a certain extent, the radiation intensity of the piping near the SRV (RV203-3B) is considered
1051 to be high. The next area that was considered to be contaminated is near the release port of SV203-4C (TC31).
1052 This leakage is estimated to have occurred at 20:26 on March 11.Asthe area of this leak was smaller than that of
1053 SV203-4A, the degree of contamination is not significantly large. A hole was formed at the bottom of the RPV
1054 at approximately 16:00 on March 12, and the injected water probably leaked out from there.

1055 If the estimation in this report is accurate, the water level in the RPV decreased below the TAF, and hot
1056 water vapor and hydrogen gas were generated; the leaked high-temperature gas resulted in sticking of the seat
1057 of the SV. The BWR is not designed for the water level to decrease below the TAF; however, the risk of the
1058 reactor water level falling below the TAF and the resulting hot gas destroying the SV must be considered, as in
1059 the Fukushima Daiichi NPP accident. If the materials of the valve seat and spring of the SVs are manufactured
1060 to withstand high temperatures, operational difficulties such as the gas tightness of the valve are also expected
1061 to arise. However, to ensure the safety of the reactor, certain operational difficulties may be acceptable.

1062 At the Fukushima Daiichi NPP, two emergency diesel generators were installed on the same floor for operational
1063 simplicity. Neither of these emergency systems functioned when the tsunami entered the R/B. Although
1064 operational difficulties are expected to arise, to prevent future accidents at NPPs, it is considered necessary
1065 to improve safety when the reactor water level decreases below the TAF.

33 VIII.

34 Conclusions

To prevent future nuclear accidents, the accident at Fukushima Daiichi NPP must be properly analyzed and understood. We had been analyzing the accident since its occurrence [2]. According to the original records and witnesses, we verified that the IC of Unit 1 of the Fukushima Daiichi NPP may have been working normally to a certain extent. Based on this assumption, we performed an accident analysis based on the accident scenario. Moreover, the behavior of the reactor water level meter at the time of the accident was analyzed, and this study attempted to reproduce the measurement data of the reactor water level meter during the accident. To contribute to the investigation of Volume Xx XI Issue I V ersion I Global Journal of Researches in Engineering () F nuclear accidents in the future, we attempted to estimate the failure locations and failure times of the RPV and PCV without fear of being accused of inaccuracy.

The predictions of the accident analysis have many possibilities under the different accident scenarios; moreover, the present predictions may not be accurate. However, there was only one true event of the accident that really happened.

The results obtained from the analysis are as follows:

1. The original data reported in the first stage of the accident and the evidence obtained from the operators were examined to clarify the behavior of the ICs. There are records that the water injection to the reservoir tank of IC-A was executed. There was a possibility that MOVs were open during the tsunami attack, and that IC-A was working after the tsunami attack until approximately 03:00 on March 12, 2011.
2. The present accident scenario estimated that the initial RPV leak occurred at 20:26 on March 11 and the pressure in the PCV increased because the steam and gas from the RPV were directly blown into the D/W. This scenario agrees with the increase in radiation intensity that was recorded in the R/B at 21:51. Owing to the increase in the PCV pressure, the PCV ruptured at approximately 03:30 and 06:23 on March 12 at the bellows of the vacuum breaker tube connecting the D/W and S/C. This estimation agrees with the radiation dosage and pressure data obtained during the accident.
3. It is estimated that the RPV ruptured at 06:20 on March 12 in the vapor phase of the vessel after the IC stopped functioning. The RPV ruptured again at approximately 16:00 at the bottom of the vessel, because the water dried out. Molten fuel may have spilled out to the PCV; however, the amount of fuel that melted was not as large as reported by TEPCO. This estimation agrees with the temperature data measured immediately after the accident and the radiation-dose data measured in the NPP.
4. The author attempted to present bold predictions of the positions and times of vessel ruptures according to the present scenario at the accident site and the temperature data in the reactor, which were obtained after March 20. The temperatures of Unit 1 increased up to 400°C on March 22, and they gradually decreased with the increase in injection water. We examined the details of the temperature data that high temperatures were recorded at several locations after water injection. Thus, we concluded that the leakages from the RPV at 20:26 on March 11 and 06:20 on March 12 occurred at the SVs, because the significantly high-temperature steam that passed through the valve destroyed the valve seat. Some of the SRVs may have suffered the same process.

IX.

35 Epilogue

It is difficult to predict the phenomena of a serious accident in real time. At the beginning of an accident, only limited data is available, and even that data is often inaccurate. The accident scenarios that are estimated from these data may be different from the truth.

During the Apollo 13 accident in 1970, the teamwork between the astronauts and the ground group resulted in the miraculous survival of the astronauts. The subsequent investigation, at least as far as the author knows, was conducted quickly and fairly, and not long after, the subsequent set of astronauts landed on the moon.

The star probe Hayabusa, which landed on the asteroid Itokawa in 2005, failed at its first landing. Based on the analysis results from that time, the landing was retried. The team on Earth estimated the conditions of Hayabusa based on the intermittent and insufficient information sent from Hayabusa and took appropriate action.

At the time of the accident at the Fukushima Daiichi NPP in 2011, Units 1-4 of the plant were only less than a kilometer away from the seismically isolated critical building where the headquarters of the task force were located; however, adequate data were not obtained. The case where the operators could not reach to the object was similar to that of Hayabusa, which stayed on the asteroid Itokawa, 300 million kilometers away from the Earth.

When faced with a serious accident, it is important to respond to the incident with flexible thinking according to the situation, similar to the actions of the Hayabusa and Apollo 13 teams. In the case of the accident at the NPP, I wonder if the concerned personnel were able to analyze and respond appropriately to the situation with a clear and flexible mind.

During the Fukushima Daiichi NPP accident, it was initially impossible to get an accurate understanding of the reactor status. Even the wrong data at the time of the accident can be corrected based on reasonable explanations to derive accident scenarios that are closer to the truth. Furthermore, by considering the new data

1126 obtained from the internal investigation of the reactor, it is possible to clarify the scenario of the accident more
 1127 accurately.

1128 Ten years after the accident, it is now possible, to a certain extent, to present scenarios that are closer to the
 1129 truth of the accident. However, from the perspective of exploring events from the still limited data, elucidating
 1130 the accidents at NPPs is somehow similar to archeology, where we look at dinosaur fossils. It is our duty as
 1131 scientists and engineers to clarify the real phenomena of the nuclear accident, and to present suggestions for
 1132 the prevention of nuclear accidents that will occur in the future. We must not distort the historical facts of the
 1133 nuclear accident for the sake of the reputation of the academician, appearances of the academic community, or
 1134 the interests of the organization. Several academic societies and organizations have published many reports on
 1135 nuclear accidents. I wonder if these reports are the result of sincere discussions among scientists and engineers
 1136 on all possibilities and an attempt to deduce the truth.

1137 In the current situation where we do not know the condition inside the reactor, there are numerous possibilities
 1138 for nuclear accident scenarios. The accident scenarios in this report can explain the data and events at the time
 1139 of the accident relatively well. However, I do not believe that all estimates and accident scenarios are accurate.
 1140 There is only one true event that actually occurred during the nuclear accident. In the future, it is necessary for
 1141 scientists and engineers to get closer to the truth by conducting serious discussions with each other.

1142 It is important to understand the actual events that occurred at the Fukushima Daiichi NPP. An accurate
 1143 understanding of the phenomena should contribute to the early termination of the nuclear accident, and prevent
 1144 similar accidents from occurring in NPPs around the world. Japan, which has suffered a significant amount of
 1145 human, financial, and cultural damage, should take the leadership in providing the world with accurate accident
 analysis and guidelines for preventing its recurrence.

1 2 3

2




Figure 1: Fig. 2 :

1146

¹© 2021 Global Journals

²() F © 2021 Global Journals III.

³() F © 2021 Global Journals




Figure 2:





Figure 3: FFig. 5 :



15

Figure 4: Around 15 :






Figure 5:




6

Figure 6: Fig. 6 :




7

Figure 7: Fig. 7 :



7

Figure 8: Figure 7



8

Figure 9: Fig. 8 :F






Figure 10:




109

Figure 11: Fig. 10 :FFig. 9 :




3

Figure 12: 3 1



12

Figure 13: Fig. 12 :



13

Figure 14: Fig. 13 :




Figure 15:





Figure 16:



1516

Figure 17: Fig. 15 : 16 :




Figure 18:




Figure 19: :




Figure 20:




Figure 21:

1

Unit Number	1	2	3	4	5	6
Nominal Power (MW)	460	784	784	784	784	1,100
Date of Operation Start	26/3/1971	18/7/1974	27/3/1976	12/10/1978	18/4/1978	10/24/1979
Type of RPV	BWR-3	BWR-4	BWR-4	BWR-4	BWR-4	BWR-5
Type of PCV	Mark I	Mark I	Mark I	Mark I	Mark I	Mark II
Main Contractor	GE	GE/Toshiba	Toshiba	Hitachi	Toshiba	GE/Toshiba
Status at the time of accident	Rated operation	Rated operation	Rated operation	Under maintenance for repairing shroud	Periodic inspection	

Figure 22: Table 1 :

2

Time	Time after Scram	Facts	Scenario Parameters
March 11 14:46	0	Earthquake, Succeeded in Scram	
14:52	0:06	IC-A,IC-B Auto Start	
14:52	0:06	Simulation Start *	
15:02	0:16	IC-A,B Manual Stop	
15:16	0:30	IC-A Manual Start	
15:18	0:32	IC-A Manual Stop	
15:22	0:36	IC-A Manual Start	
15:25	0:39	IC-A Manual Stop	
15:31	0:45	IC-A Manual Start	
15:34	0:48	IC-A Manual Stop	
15:36:59	0:59:59	Tsunami Attack, AC Blackout	
15:50	1:04	DC Blackout	
15:59	1:13	SRV Blow*	

[Note: F© 2021 Global Journals]

Figure 23: Table 2 :

2

14.2, 2011/5/11] has undergone multiple changes since March11, 2011.

Figure 24: Table 2

3

TC No.	Name	Tag. No	Service Name	Position	Direction	Height
20	Vessel Flange	TE-263-66B1	Vessel Head Flange	RPV	270	33000
21	Vessel Flange(Vessel Stream)	TE-263-67A1	Vessel Stud	RPV	270	33000
22	Water Supply Nozzle N4B (Terminal)	TE-263-69D1	N4B Nozzle End	RPV	135	27750
23	Water Supply Nozzle N4B(Inner)	TE-263-69D2	N4B Nozzle End In-board	RPV		
24	Water Supply Nozzle N4C(Terminal)	TE-263-69E1	N4C Nozzle End	RPV	225	27750
25	Water Supply Nozzle N4C (Inner)	TE-263-69E2	N4C Nozzle End In-board	RPV		
26	Vessel Core	TE-263-69F3	Vessel Core	RPV	270	22160
27	RPV Lower Part (Lower Head)	TE-263-69L1 or 69L2	Vessel Bottom Head	RPV	25	1550 or 130
28	Control Rod Drive (CRD) Upper Housing	TE-263-69N1	CRD Housing Top Edge	RPV		
29	CRD Lower Housing	TE-263-69N3	CRD Housing Top Edge	RPV		
30	SV Exhaust 203-4A?	TE-261-13A	SV-4A	PCV(D/W)		
31	SV Exhaust 203-4C?	TE-261-13C	SV-4C	PCV(D/W)		
32	SV Exhaust 203-4B?	TE-261-13B	SV-4B	PCV(D/W)		
33	SRV Exhaust 203-3A?	TE-261-14A	RV-203-3A(Blowdown Valve)	PCV(D/W)		
34	SRV Exhaust 203-3B?	TE-261-14B	RV-203-3B (Blowdown Valve)	PCV(D/W)		
35	SRV Exhaust 203-3C?	TE-261-14B	RV-203-3C (Blowdown Valve)	PCV(D/W)		
36	SRV Exhaust 203-3D?	TE-261-14B	RV-203-3D(Blowdown Valve)	PCV(D/W)		
39	HVH-12CReturn	TE-1625C	HVH-12C Return Air	PCV(D/W)		
41	RPV Bellow Seal(HVH-12A 1625L) HVH-12A?	TE-1625A	HVH-12A Return Air	PCV(D/W)		
43	S/C Pool Water			PCV(S/C)		

Figure 25: Table 3 :

4

Type of Valve	Name in Fig. 16(c)	Operating Pressure (MPa)
Safety Valve (SV)	203-4A, 203-4C	8.51
Safety Valve (SV)	203-4B	8.62
Safety Relief Valve (SRV)	203-3B, 203-3C	7.64
Safety Relief Valve (SRV)	203-3A, 203-3D	7.71

Figure 26: Table 4 :

1 Acknowledgments

I would like to express my gratitude to colleagues and professors of academic societies who provided me with various information that aided in producing this report. The faculty members and students of my laboratory helped to arrange and analyze the data. In particular, I would like to thank the students who stayed in Sendai during the accident and helped us as a contribution to society, instead of going to volunteer for disaster recovery. I would also like to express my gratitude to Mr. Shuichi Moriya, a technical staff member of my laboratory, for his assistance in preparing the figures.

2 Abbreviations

[Tokyo Electric Power Company (TEPCO), Fukushima Nuclear Accident Analysis Report] , *Tokyo Electric Power Company (TEPCO), Fukushima Nuclear Accident Analysis Report* p. 20.

[White and Mechanics ()] , F M White , *Fluid Mechanics* . 1999. McGraw Hill. p. 397.

[Analysis of the TEPCO Fukushima Daiichi NPS Accident, Interim Report (Provisional Translation) (2014)] , https://www.iaea.org/sites/default/files/anaylisis_nra1014.pdf *Analysis of the TEPCO Fukushima Daiichi NPS Accident, Interim Report (Provisional Translation)* October 2014. Nuclear Regulation Authority of Japan

[Analysis and impact assessment of Fukushima Daiichi Nuclear Power Plant operation records and accident records at the time of 'Analysis and impact assessment of Fukushima Daiichi Nuclear Power Plant operation records and accident records at the time of the Great East Japan Earthquake'. https://www.tepco.co.jp/cc/press/betu11_j/images/1_10524a.pdf 4. *Government of Japan, Investigation Committee on the Accident at Fukushima Nuclear Power Stations of Tokyo Electric Power Company, Interim report*, 23 May 2011. p. 26. Tokyo Electric Power Company (TEPCO (in Japanese)

[Liepmann and Roshko ()] *Elements of Gasdynamics*, H W Liepmann , A Roshko . 1956. John Willey & Sons. p. .

[Evaluation of the situation of cores and containment vessels of Fukushima Daiichi Nuclear Power Station Units-1 to 3 and examination into unsolved issues in the accident progression, p. 13. Tokyo Electric Power Company (TEPCO) (Progress Report)

[Evaluation of the situation of cores and containment vessels of Fukushima Daiichi Nuclear Power Station Units-1 to 3 and examination into unsolved issues in the accident progression, p. 17. Tokyo Electric Power Company (TEPCO) (Progress Report)

[Evaluation of the situation of cores and containment vessels of Fukushima Daiichi Nuclear Power Station Units-1 to 3 and examination into unsolved issues in the accident progression, https://www.tepco.co.jp/en/press/corp-com/release/betu15_e/images/150520e0102.pdf 20 May 2015. Tokyo Electric Power Company (TEPCO) (Progress Report)

[Evaluation of the situation of cores and containment vessels of Fukushima Daiichi Nuclear Power Station Units-1 to 3 and examination into unsolved issues in the accident progression, https://www.tepco.co.jp/en/press/corp-com/release/betu17_e/images/171225e0201.pdf 25 December 2017. Tokyo Electric Power Company (TEPCO) (Progress Report)

[Evaluation of the situation of cores and containment vessels of Fukushima Daiichi Nuclear Power Station Units-1 to 3 and examination into unsolved issues in the accident progression, https://www.tepco.co.jp/en/press/corp-com/release/betu14_e/images/140806e0102.pdf 6 August 2014. Tokyo Electric Power Company (TEPCO) (Progress Report)

[Maruyama and Fukushima; Anovel (2011)] *Government of Japan, Investigation Committee on the Accident at Fukushima Nuclear Power Stations of Tokyo Electric Power Company, Hearing records*, S Maruyama , Yokendo Fukushima; Anovel . https://www8.cao.go.jp/genshiryoku_bousai/fu_koukai/fu_koukai_2.html#a August 2012. 21 July 2011 -26 June 2012. (in Japanese. in Japanese)

[Maruyama ()] 'Heat and fluid flow in accident of Fukushima Daiichi nuclear power plant, Unit 1 (Behavior of isolation condensers (ICs) based on thermodynamic model)'. S Maruyama . https://www.jstage.jst.go.jp/article/transjsme/80/820/80_2014tep0377/_pdf/-char/ja *Transactions of JSME* 2014. 80 (820) . (in Japanese)

[Maruyama ()] *Heat and fluid flow in accident of Fukushima Daiichi Nuclear Power Plant, Unit 1 -When the isolation condenser was working-, Maintenology*, S Maruyama . <https://mainte-archive.cloud/006140> 2012. 11 p. . (in Japanese)

- 1204 [Maruyama ()] *Heat and fluid flow in accident of Fukushima Daiichi nuclear power plant, Unit 3 -When the*
 1205 *high-pressure coolant injection system (HPCI) stopped-, Maintenology*, S Maruyama . [Users/maruyama/](#)
 1206 [Downloads/HZN_001_20121001_100_01.pdf](#) 2012. 11 p. . (in Japanese)
- 1207 [Maruyama ()] ‘Heat and fluid flow in in accident of Fukushima Daiichi nuclear power plant, Unit 2 (Accident
 1208 scenario based on thermodynamic model)’. S Maruyama . *Transactions of JSME, Series B* 2012. 78 (796) p.
 1209 . (in Japanese)
- 1210 [Interim report on investigation and analysis of TEPCO Fukushima Daiichi nuclear power plant accident (draft) Nuclear Regulati
 1211 ‘Interim report on investigation and analysis of TEPCO Fukushima Daiichi nuclear power plant accident
 1212 (draft)’. *Nuclear Regulation Authority of Japan* 18 December 2020. (in Japanese)
- 1213 [List of plant data collected by the operator during the accident Tokyo Electric Power Company (TEPCO), Fukushima Nuclear A
 1214 ‘List of plant data collected by the operator during the accident’. <https://www.tepco.co.jp/decom>
 1215 *Tokyo Electric Power Company (TEPCO), Fukushima Nuclear Accident Analysis Report, Intermediate*
 1216 *Report, Attachment*, 27 November 2011. 2 December 2011. Tokyo Electric Power Company (TEPCO) (in
 1217 Japanese. in Japanese)
- 1218 [References Références Referencias 1. National Police Agency of Japan, Police countermeasures and damage situation associated v
 1219 *References Références Referencias 1. National Police Agency of Japan, Police countermeasures*
 1220 *and damage situation associated with 2011Tohoku district -off the Pacific Ocean earth quake,*
 1221 http://www.npa.go.jp/news/other/earthquake2011/pdf/higaijokyo_e.pdf February 10,
 1222 2021.
- 1223 [Temperature data of various measurement points in Unit 1 (2011)] *Temperature data of various measurement*
 1224 *points in Unit 1*, 17 May 2011. Tokyo Electric Power Company (TEPCO)
- 1225 [The Fukushima Daiichi accident, Report by the director general International Atomic Energy Agency (IAEA) (2015)]
 1226 ‘The Fukushima Daiichi accident, Report by the director general’. [https://www-pub.iaea.org/mtcd/](https://www-pub.iaea.org/mtcd/publications/pdf/pub1710-reportbythedg-web.pdf)
 1227 [publications/pdf/pub1710-reportbythedg-web.pdf](https://www-pub.iaea.org/mtcd/publications/pdf/pub1710-reportbythedg-web.pdf) *International Atomic Energy Agency (IAEA)*
 1228 August 2015.
- 1229 [The Fukushima Daiichi nuclear accident, Final report of the AESJ investigation committee Atomic Energy Society of Japan ()]
 1230 ‘The Fukushima Daiichi nuclear accident, Final report of the AESJ investigation committee’. *Atomic Energy*
 1231 *Society of Japan* 2015. March 2014. Springer.
- 1232 [The official report of the Fukushima Nuclear Accident Independent Investigation Commission TEPCO, Proposed revision of the
 1233 ‘The official report of the Fukushima Nuclear Accident Independent Investigation Commission’.
 1234 https://www.nirs.org/wp-content/uploads/fukushima/naic_report.pdf *TEPCO, Proposed*
 1235 *revision of the medium-and long-term roadmap for decommissioning of the Fukushima Daiichi Nuclear Power*
 1236 *Plant*, 27 December 2019. 11 March 2012. National Diet of Japan (in Japanese)
- 1237 [Maruyama et al. ()] *Thermal analysis and control plan of the accident of Fukushima Daiichi Nuclear Power*
 1238 *Plant*, S Maruyama , A Komiya , J Okajima . [http://www.ifs.tohoku.ac.jp/komiya/maru/atom/](http://www.ifs.tohoku.ac.jp/komiya/maru/atom/index.html)
 1239 [index.html](http://www.ifs.tohoku.ac.jp/komiya/maru/atom/index.html) 2011-2015.. Heat Transfer Control Laboratory, Institute of Fluid Science, Tohoku University
 1240 (in Japanese)
- 1241 [Maruyama ()] *Thermal Science for Everyone*, S Maruyama . 2015. (in Japanese)
- 1242 [Time series data concerning the status of reactors at each unit of Fukushima Daiichi and Fukushima Daini NPPs submitted from
 1243 ‘Time series data concerning the status of reactors at each unit of Fukushima Daiichi and Fukushima Daini
 1244 NPPs submitted from TEPCO’. [https://www.nsr.go.jp/activity/bousai/trouble/gensai_25/](https://www.nsr.go.jp/activity/bousai/trouble/gensai_25/archive_nisa/index.html)
 1245 [archive_nisa/index.html](https://www.nsr.go.jp/activity/bousai/trouble/gensai_25/archive_nisa/index.html) *Global Journals 26. Nuclear and Industrial Safety Agency (NISA)*, June
 1246 2011. June 24, 2011. 18. Tokyo Electric Power Company (TEPCO), Fukushima Daiichi Nuclear Power Plant
 1247 (Situation of the response immediately after the disaster. in Japanese)
- 1248 [Maruyama ()] ‘Unit 3 (Behavior of high pressure coolant injection system (HPCI) based on thermody-
 1249 namic model)’. S Maruyama . [https://www.jstage.jst.go.jp/article/transjsme/80/814/80_](https://www.jstage.jst.go.jp/article/transjsme/80/814/80_2014tep0155/_pdf/-char/ja)
 1250 [2014tep0155/_pdf/-char/ja](https://www.jstage.jst.go.jp/article/transjsme/80/814/80_2014tep0155/_pdf/-char/ja) *Transactions of the JSME*, 2014. 80. (Heat and fluid flow in accident of
 1251 Fukushima Daiichi nuclear power plant. in Japanese)